

Spill Dimensions		
L(Ft)	W(Ft)	D(in)
144	7	1

  

Results	
Spill Before Disp (Bbls):	<b>14.96</b>
Tank Displacement Vol (Bbls):	<b>0.00</b>
Total Spill Bbls:	<b>14.96</b>

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 536345

**QUESTIONS**

Operator: HF Sinclair Navajo Refining LLC ATTN: GENERAL COUNSEL Dallas, TX 75201	OGRID: 15694
	Action Number: 536345
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

Prerequisites	
Incident ID (n#)	nAPP2534932042
Incident Name	NAPP2534932042 HF SINCLAIR NAVAJO REFINERY LLC @ E-09-17S-26E
Incident Type	Other
Incident Status	Initial C-141 Received

**Location of Release Source**

*Please answer all the questions in this group.*

Site Name	HF Sinclair Navajo Refinery LLC
Date Release Discovered	12/14/2025
Surface Owner	Private

**Incident Details**

*Please answer all the questions in this group.*

Incident Type	Other
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

**Nature and Volume of Release**

*Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.*

Crude Oil Released (bbls) Details	Not answered.
Produced Water Released (bbls) Details	Not answered.
Is the concentration of chloride in the produced water >10,000 mg/l	No
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Cause: Overflow - Tank, Pit, Etc.   Other (Specify)   Other (Specify)   Released: 15 BBL   Recovered: 15 BBL   Lost: 0 BBL.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	On December 14, 2025, a sewer at HF Sinclair Navajo Refining LLC's onsite wastewater treatment plant (WWTP) backed up causing approximately 15 bbls of oily water to flow outside of containment onto soil. Liquid was removed via vacuum truck and impacted soil was scraped into a container for waste characterization and offsite disposal. There was no offsite impact.

**State of New Mexico**  
**Energy, Minerals and Natural**  
**Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 536345

Sante Fe Main Office  
 Phone: (505) 476-3441  
 General Information  
 Phone: (505) 629-6116  
 Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**QUESTIONS (continued)**

Operator:  
 HF Sinclair Navajo Refining LLC  
 ATTN: GENERAL COUNSEL  
 Dallas, TX 75201

OGRID:  
 15694  
 Action Number:  
 536345  
 Action Type:  
 [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

<b>Nature and Volume of Release (continued)</b>	
Is this a gas only submission (i.e. only significant Mcf values reported)	<b>No, according to supplied volumes this does not appear to be a "gas only" report.</b>
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	<b>No</b>
Reasons why this would be considered a submission for a notification of a major release	Unavailable.

With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.

<b>Initial Response</b>	
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.	
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Material collected for staging and waste characterization for transport and appropriate disposal.

*Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all

operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Teresa Alba Title: Environmental Supervisor Email: <a href="mailto:Teresa.Alba@HFSinclair.com">Teresa.Alba@HFSinclair.com</a> Date: 12/19/2025
--	---

**State of New Mexico**  
**Energy, Minerals and Natural**  
**Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 536345

Sante Fe Main Office  
 Phone: (505) 476-3441  
 General Information  
 Phone: (505) 629-6116  
 Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**QUESTIONS (continued)**

Operator:  
 HF Sinclair Navajo Refining LLC  
 ATTN: GENERAL COUNSEL  
 Dallas, TX 75201

OGRID:  
 15694  
 Action Number:  
 536345  
 Action Type:  
 [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

<b>Site Characterization</b>	
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.	
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.
What method was used to determine the depth to ground water	Not answered.
Did this release impact groundwater or surface water	Not answered.
<b>What is the minimum distance, between the closest lateral extents of the release and the following surface areas:</b>	
A continuously flowing watercourse or any other significant watercourse	Not answered.
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.
An occupied permanent residence, school, hospital, institution, or church	Not answered.
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.
Any other fresh water well or spring	Not answered.
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.
A wetland	Not answered.
A subsurface mine	Not answered.
An (non-karst) unstable area	Not answered.
Categorize the risk of this well / site being in a karst geology	Not answered.
A 100-year floodplain	Not answered.
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.

<b>Remediation Plan</b>	
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.	
Requesting a remediation plan approval with this submission	No
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.	

**State of New Mexico  
Energy, Minerals and Natural  
Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505**

CONDITIONS

Sante Fe Main Office  
Phone: (505) 476-3441  
General Information  
Phone: (505) 629-6116  
Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

Action 536345

**CONDITIONS**

Operator:  
HF Sinclair Navajo Refining LLC  
ATTN: GENERAL COUNSEL  
Dallas, TX 75201

OGRID:  
15694  
Action Number:  
536345  
Action Type:  
[C-141] Initial C-141 (C-141-v-Initial)

**CONDITIONS**

Created By Condition  
scott.rodgers None

Condition  
Date  
12/22/2025