

1. WELL API NO. 30-039-30926
2. Well Name: SAN JUAN 27 4 UNIT #150M
3. Well Number: 150M
4. Surface Hole Location: Unit:F Lot:F Section:36 Township:27N Range:04W Feet from:1512 N/S Line:N Feet from:1503 E/W Line:W
5. Bottom Hole Location: Unit:F Lot:F Section:36 Township:27N Range:04W Feet from:1512 N/S Line:N Feet from:1503 E/W Line:W
6. latitude: 0 longitude: 0
7. County: Rio Arriba

8. Operator Name and Address: BURLINGTON RESOURCES OIL & GAS COMPANY LP 3401 E. 30TH STREET FARMINGTON 87402	9. OGRID: 14538	10. Phone Number: 505-326-9518
---	--------------------	-----------------------------------

11. Last Fracture Date: 5/16/2012	Frac Performed by: BAKER HUGHES	12. Production Type: C
-----------------------------------	---------------------------------	------------------------

13. Pool Code(s): 71500, 70240	14. Gross Fractured Interval: 5,024 # to 9,624 #
-----------------------------------	---

71599, 72319	5,834 ft to 8,634 ft
15. True Vertical Depth (TVD): 8,636 ft	16. Total Volume of Fluid Pumped: 1,094 bbls

4.7. HYDRAULIC FLUID COMPOSITION AND CONCENTRATION:

[illegible]

18. I, as Operator, hereby certify that the information shown on this disclosure form is true and complete to the best of my knowledge and belief.

Signature: Signed Electronically Printed Name: Denise D Journey Title: Regulatory Technician
Date: 7/26/2012
E-mail Address: Denise.Journey@conocophillips.com