| Submit 3 Copies To Appropriate District | State of N | New Me | xico | | Form C-103 | | |
|--|---|---------------------|----------------------------|--|-----------------|--|--|
| Office District I | Energy, Minerals a | and Natu | ral Resources | | May 27, 2004 | | |
| 1625 N. French Dr., Hobbs, NM 88240 District II | | | | WELL API NO. 30-021-20591 | | | |
| 1301 W. Grand Ave., Artesia, NM 88210 District III | OIL CONSERVATION DIVISION 1220 South St. Francis Dr. | | | 5. Indicate Type of Lease | | | |
| <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 | | | | | EE | | |
| <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505 | Santa Fe | , INI VI 8 7 | 6. State Oil & Gas Lease I | NO. | | | |
| SUNDRY NOTIO | 7. Lease Name or Unit Agreement Name | | | | | | |
| (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC. | Libba Minamla LLC 2021 | | | | | | |
| PROPOSALS.) | Libby Minerals LLC 2031 8. Well Number 18-1-M | | | | | | |
| 1. Type of Well: Oil Well | 9. OGRID Number | | | | | | |
| 2. Name of Operator Reliant Exploration & Production, I | 251905 | | | | | | |
| 3. Address of Operator | 10. Pool name or Wildcat | | | | | | |
| 10817 West County Road 60 Midlan | Bravo Dome 96010 | | | | | | |
| 4. Well Location | | | | | | | |
| | _700feet from the | | | | Westline | | |
| Section 18 | Township | | Range 31 | and the second | unty Harding | | |
| | 11. Elevation (Show whee 4529 | etner DR, | RKB, KI, GR, etc. |) | | | |
| Pit or Below-grade Tank Application 🗌 or | | | | | | | |
| Pit typeDepth to Groundwa | terDistance from near | rest fresh w | ater well Dis | tance from nearest surface water_ | | | |
| Pit Liner Thickness: mil | Below-Grade Tank: Vol | ume | bbls; Co | onstruction Material | | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | | | | | |
| NOTICE OF IN | TENTION TO: | | SUB | SEQUENT REPORT | OF: | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | | REMEDIAL WOR | | | | |
| TEMPORARILY ABANDON | CHANGE PLANS | | COMMENCE DR | _ | A 🗌 | | |
| PULL OR ALTER CASING | MULTIPLE COMPL | | CASING/CEMEN | T JOB | | | |
| OTHER: | | | OTHER: | | | | |
| Describe proposed or compl of starting any proposed wor or recompletion. | | | | | | | |
| | | | | | | | |
| See Attachment | | | | tens tens | | | |
| | | | | 6.7 | | | |
| | | | | | | | |
| | | | | مەرىيى لىرمىي | | | |
| | | | | · • • • • • | - | | |
| | | | | | 00D | | |
| | | | | ы С | 3 | | |
| | | | | ස් ස | <u> </u> | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . | | | | | | | |
| - | - | | | | | | |
| SIGNATURE | | TITLE | Maryer | DATE | 1-10-19 | | |
| Type or print name Vance V | anderburg | E-mail ad | idress: Kurerel | DATE DATE | No. 432-559-708 | | |

| For State Use Only | | | |
|---------------------------------|---------|--------------------------|-----------------|
| | Martino | DISTRICT SUPERVISOR | DATE 1/20/2014 |
| APPROVED BY: | artino | DIGITIOT OUT ENVIOUN | _DATE 1/21/2019 |
| Conditions of Approval (if any) | | | , , |

Libby Minerals LLC 1931 18-1-M

12/18/13

(06:00)MIRU Reliant Rig #1. KB = 10' AGL.

Inspected rig, drill collars, and drill pipe.

12/19/13

Spud in at (10:00) / Drill 12.25" surface hole from 0' to 754' / Average WOB 10 / 95-100 RTS / 370 gpm @ 960 psi.

(23:00) Circulate

12/20/13

(00:00) TOOH

(02:00)Ran 8.625, 24.0 lb/ft, J-55, ST&C, from 10' to 726'.

(04:00) Circulate

(05:00) MIRU O-Tex to pump surface cement job as follows:

Pressure tested lines to 2000 psi. Pumped 10 bbl spacer. Pumped 440 sks of Class C + 2% Calcium chloride cement at 14.8 ppg at 3 BPM and100 psi. Dropped top plug and pumped 43 bbls displacement at 3 BPM and 120 psi. Bumped plug to 1100 psi. Float held. Circulated a total of 55 bbls to surface. Plug down at 06:45 hours on 12/20/2013. WOC

12/21/13

(11:00)Remove landing joint and nipple up BOP. Release hands for holidays.

1/06/14

(18:30)TIH

1/07/14

(001:30) Drilled 7 7/8 production hole from 754' to 2021' / Average WOB 10 / 100 RTS / 335 gpm @ 850 psi.

1/08/14

Drilled 7 7/8 production hole from 2021' to 2225' / Average WOB 12 / 100 RTS / 350 gpm @ 950 psi.

(04:15) Circulate. Wait on loggers tied up on other job.

(11:00) TOOH

(14:00) Wait on Halliburton wire line to run open hole logs.

(15:00) MIRU Halliburton wire line to run open hole logs.

(20:30)Ran 5 ½ casing as follows: 5.5", 15.5#, J-55, 8 RD, casing from 8' to 2201'.

01/09/14

(02:00)Circulate and Condition hole

(02:30)MIRU O-Tex to pump cement as follows:

Pressure tested lines to 3500 psi. Pump 10 bbls spacer. Pumped 210 sks lead cement Class C + 2% GYP + 3%Calcl2 + 2% SM + 1/8 lb per sk celloflake at 11.1 ppg at 3 bpm at 100 psi. Pumped 105 sks tail cement Class C + 2% GYP + 3%Calcl2 + 2% SM + 1/8 lb per sk celloflake at 13.2 ppg at 3 bpm at 80 psi. Dropped top plug. Displaced cement with 52 bbls water at 3 bpm and 50 psi. Bumped plug at 1000 psi.. Float equipment held. Circulated 60 bbls to surface. Plug down at 04:10 hours on 1/09/14.

(08:00) Nipple down BOP equipment and clean pits and location.

Rig released at 12:00 hours on 1/09/14.



January 10, 2014

Mr. Ed Martin District IV Supervisor New Mexico Oil Conservation Division 1220 South St. Francis Santa Fe, NM 87505

Re: Form C-103

Dear Mr. Martin:

Please find enclosed for your approval Form C-103 for the following well;

Libby Minerals LLC 2031 18-1-M.

Please send the approved 103's to my attention at the following address;

7714 Georgetown Drive

Amarillo, TX 79119

Please let me know if you have any questions.

Sincerely,

Ve Velo

Vance Vanderburg vance@reliantholdingsltd.com 432-559-7085