

District 2-Artesia Field Office
811 S. 1st Street
Artesia, NM 88210
(Office) 575-748-1283
(Fax) 575-748-9720
Submit 1 Copy

State of New Mexico

EMNRD-OIL CONSERVATION DIVISION

BRADENHEAD TEST REPORT

Operator Name Trinity Environmental SWD 1, LLC	³⁰ API Number 30-015-32585
Property Name OXY DOC SLAWIN FEDERAL	Well No. #2

⁷ Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
I	29	17S	31E	1780	S	660	E	EDDY

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES NO	INJ SWD	OIL GAS	11-4-2020

OBSERVED DATA


	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	1300 PSI SHUT IN
Flow Characteristics					
Puff	Y/ N	Y/ N	Y/ N	Y/ N	CO2 <u> </u>
Steady Flow	Y/ N	Y/ N	Y/ N	Y/ N	WTR <u>X</u>
Surges	Y/ N	Y/ N	Y/ N	Y/ N	GAS <u> </u>
Down to nothing	Y/ N	Y/ N	Y/ N	Y/ N	If applicable type
Gas or Oil	Y/ N	Y/ N	Y/ N	Y/ N	fluid injected for
Water	Y/ N	Y/ N	Y/ N	Y/ N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.
NO PRESSURE ON CASING.

Accepted for record test not witnessed
NMOCD DS 12-1-2020

Signature:  Print name: Kevin W. Rogers Title: Operations Manager E-mail Address: kevin.rogers@trinityenv.com Phone #: 575-200-7896 Date: 11-5-2020 Witness:	OIL CONSERVATION DIVISION Recorded online: Re-test:
---	--