



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrld.state.nm.us/ocd/District III/district.htm](http://emrld.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2/11/21 Operator HILCORP ENERGY API #30-0 45-34454

Property Name CANYON SWD Well No. 1 Location: Unit N Section 35 Township 26N Range 11W

Well Status(Shut-In or Producing) Initial PSI: Tubing 553 Intermediate N/A Casing 0 Bradenhead 42

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>0</u>		
10 min	<u>0</u>	<u>-</u>	<u>0</u>		
15 min	<u>0</u>	<u>-</u>	<u>0</u>		
20 min	<u>0</u>	<u>-</u>	<u>0</u>		
25 min	<u>0</u>	<u>-</u>	<u>0</u>		
30 min	<u>0</u>	<u>-</u>	<u>0</u>		
				Steady Flow	
				Surges	
				Down to Nothing	<u>X</u>
				Nothing	
				Gas	<u>X</u>
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH down to 0 33 sec.
Nothing after 5min shut
MONICA K. WITNESSED VIA FACETIME. NO GAS SAMPLE REQUIRED PER MONICA.
By LESTER P / STEVE J. Witness MONICA KEWLING
SWD
(Position)

E-mail address LPIPKINS@HILCORP.COM
SJAQUER@HILCORP.COM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 17897

CONDITIONS OF APPROVAL

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX77002			OGRID: 372171	Action Number: 17897	Action Type: BRADENHEAD TEST (3)
OCD Reviewer	Condition				
mkuehling	no water found - full 30 minute test ran - no gas analysis required at this time				