

District I

1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S 1st Street, Artesia, NM 88210
Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN LTD	API Number 30-015-41886
Property Name DEVON 8 FEE	Well No. 003H

Surface Location

UL -Lot M	Section 8	Township 25S	Range 28E		Feet From 572	N/S Line S	Feet From 392	E/W Line W	County EDDY
--------------	--------------	-----------------	--------------	--	------------------	---------------	------------------	---------------	----------------

TA'D Well Yes	SHUT-IN No	INJECTOR INJ	PRODUCING OIL	DATE 1/18/2021
------------------	---------------	-----------------	------------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	<u>(A) Surf-Interm</u>	<u>(B)Interm-Interm(2)</u>	<u>(C)Internm-Prod</u>	<u>(D)Prod Csgng</u>	<u>(E)Tubing</u>
Pressure	0	0		890	48
<u>Flow Characteristics</u>					CO ₂ N/A
Puff	N	N	N/A	N/A	WTR N/A
Steady Flow	Y	N	N/A	N/A	GAS N/A
Surges	N	N	N/A	N/A	Type of Fluid
Down to nothing	Y	Y	N/A	N/A	Injected for
Gas or Oil	N	N	N/A	N/A	Water Flood if
Water	N	N	N/A	N/A	applies

Remarks - Please state for each string (A,V,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Arrived at well location installed gauge on surface interm opened valve recorded pressure 340 bleed down pressure no water. Surface interm bleed off in approx 2 minutes. Installed gauge monitored for 15 minutes no change (no pressure build up was observed) recorded pressure at 0lbs. Opened up surface interm #2 valve no pressure was observed installed gauge, monitored 15 minutes no change recorded pressure at 0.

Signature: <i>Colton Burch</i>	OIL CONSERVATION DIVISION	
Printed name: Colton Burch	Entered into RBDMS	
Title: Production Tech	Re-test	
E-mail Address: colton_burch@oxy.com		
Date: 1/18/2021	Phone: 575-361-7168	
	Witness:	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 19342

CONDITIONS OF APPROVAL

Operator:	OCCIDENTAL PERMIAN LTD	P.O. Box 4294	Houston, TX772104294	OGRID:	157984	Action Number:	19342	Action Type:	C-103Z
OCD Reviewer	Condition								
ksimmons	None								