

Well Name: SAN JUAN 30-6 UNIT	Well Location: T30N / R7W / SEC 22 / SESE / 36.793877 / 107.553561	County or Parish/State: RIO ARRIBA / NM
Well Number: 466S	Type of Well: OTHER	Allottee or Tribe Name:
Lease Number: NMSF079382	Unit or CA Name: SAN JUAN 30-6 UNIT--FR	Unit or CA Number: NMNM78420B
US Well Number: 300392941100S1	Well Status: Temporarily Abandoned	Operator: HILCORP ENERGY COMPANY

Subsequent Report

Type of Submission: Subsequent Report	Type of Action: Mechanical Integrity Test
Date Sundry Submitted: 01/27/2021	Time Sundry Submitted: 02:26
Date Operation Actually Began: 01/26/2021	

Actual Procedure: A Mechanical Integrity Test (MIT) was performed on 1/26/2021 for subject well. PT to 558psi for 30mins. Test good. Witnessed by Jonathan Kelly (NMOCD) via facetime. Please see attached chart.

SR Attachments

Actual Procedure

San_Juan_30_6_UNIT_466S_MIT_Chart_1_26_20_20210127141759.pdf

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: TRUJILLO	Signed on: JAN 27, 2021 02:24 PM
Name: HILCORP ENERGY COMPANY	
Title: Senior Operations/Regulatory Technician	
Street Address: 1111 Travis Street	
City: Houston	State: TX
Phone: (713) 209-2400	
Email address:	

Field Representative

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

Well Name: SAN JUAN 30-6 UNIT	Well Location: T30N / R7W / SEC 22 / SESE / 36.793877 / 107.553561	County or Parish/State: RIO ARriba / NM
Well Number: 466S	Type of Well: OTHER	Allottee or Tribe Name:
Lease Number: NMSF079382	Unit or CA Name: SAN JUAN 30-6 UNIT--FR	Unit or CA Number: NMNM78420B
US Well Number: 300392941100S1	Well Status: Temporarily Abandoned	Operator: HILCORP ENERGY COMPANY

BLM Point of Contact

BLM POC Name: JOE D KILLINS

BLM POC Phone: 5055647731


Disposition: Accepted

Signature: Joe Killins

BLM POC Title: Petroleum Engineer

BLM POC Email Address: jkillins@blm.gov

Disposition Date: 02/26/2021



District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 19151

COMMENTS

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	19151	C-103Z

Created By	Comment	Comment Date
ahvermersch	NMOCD TA EXPIRES 1-26-26	03/23/2021

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 19151

CONDITIONS OF APPROVAL

Operator:	HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	OGRID:	372171	Action Number:	19151	Action Type:	C-103Z
OCD Reviewer	Condition								
mkuehling	None								