

Office
 District I – (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II – (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III – (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV – (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM
 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-021-20390
1. Type of Well: Oil Well ☐ Gas Well ☒ Other- CO2 PRODUCER		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator OXY USA INC.		6. State Oil & Gas Lease No.
3. Address of Operator P.O. BOX 50250 MIDLAND, TX 79710		7. Lease Name or Unit Agreement Name Bravo Dome Carbon Dioxide Gas Unit
4. Well Location Unit Letter <u>G</u> : <u>1700</u> feet from the <u>NORTH</u> line and <u>1700</u> feet from the <u>EAST</u> line Section <u>20</u> Township <u>18N</u> Range <u>32E</u> NMPM County <u>HARDING</u>		8. Well Number: 201
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4521' GR		9. OGRID Number: 16696
10. Pool name or Wildcat: Bravo Dome Carbon Dioxide Gas 640		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
DOWNHOLE COMMINGLE ☐			
CLOSED-LOOP SYSTEM ☐			
OTHER: TA EXTENSION-MIT ☒		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

OXY USA INC respectfully requests a five year Temporarily Abandon Status Extension from the current TA expiration date of 09/30/2020. Plan forward is as follows:

1. Set retrievable bridge plug ~50' above top perf
2. Notify NMOCD of casing integrity test 24hours in advance to witness test
3. RU pump truck, circulate well with treated water, pressure test casing to 500 psi for 30 min

THIS IS A MONITOR WELL.

Spud Date: Rig Release Date:


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE: Sr. Regulatory Analyst DATE: 09/03/2021

Type or print name: Jana Mendiola E-mail address: janalyn_mendiola@oxy.com PHONE: 432-685-5936
For State Use Only

APPROVED BY: Monica Kushling TITLE: Deputy Oil and Gas Inspector DATE: 9/9/2021
 Conditions of Approval (if any):

OXY USA Inc. - Current
Bravo Dome CO2 Gas Unit # 201
API No. 30-021-20390



Spud 06/03/2008

12-1/4" hole @ 735'
8-5/8"24# csg @ 730'
w/ 400sx-TOC-Surf-Circ.


7-7/8" hole @ 2290'
5-1/2" 5.9#FG/15.5# csg @ 2273'
w/ 450sx - TOC-Surf-Circ.

Perfs 2220' - 2240'

PBTD - 2262'

TD - 2290'

OXY USA Inc. - Proposed
Bravo Dome CO2 Gas Unit # 201
API No. 30-021-20390



District I

1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 46468

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 46468
	Action Type: [C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	NMOCD witness required on all testing. Northwest bradenhead test required prior to MIT - performed day of MIT - all valves need to be dug out and plumbed to surface - do not bury till after testing - chart recorder with 1000 lb spring - 1 hour clock - chart should match spring and clock	9/9/2021