

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-4-2021 Operator Jed Jones API #30-0 1529780Property Name Hackberry 18 Fed Well No. 1 Location: Unit Section 18 Township 19S Range 31EWell Status (Shut-In) or Producing) Initial PSI: Tubing Intermediate Casing 200 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0	0				Steady Flow	
10 min	0	0				Surges	
15 min	0	0				Down to Nothing	
20 min						Nothing	✓
25 min						Gas	✓
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE REMARKS: No PSI on Bradenhead or Intermediate
and no build up during bleed down.By Jed JonesWitness Lead operator

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 60496

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 60496
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	1/14/2022