Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: SAN JUAN 32-8 UNIT Well Location: T31N / R8W / SEC 14 / County or Parish/State: SAN

Well Number: 303 Type of Well: INJECTION - ENHANCED Allottee or Tribe Name:

RECOVERY

Lease Number: NMSF079047 Unit or CA Name: Unit or CA Number:

US Well Number: 3004528703 Well Status: Water Injection Well Operator: HILCORP ENERGY

COMPANY

Subsequent Report

Sundry ID: 2631007

Type of Submission: Subsequent Report

Type of Action: Workover Operations

Date Sundry Submitted: 08/27/2021 Time Sundry Submitted: 08:17

Date Operation Actually Began: 07/19/2021

Actual Procedure: Attached please find the packer repair operations and subsequent MIT that was performed on the subject well.

SR Attachments

Actual Procedure

SJ_32_8_UNIT_303_SWD_PKR_REPAIR_SR_20210827081717.pdf

Received by OCD: 9/13/2021 11:18:46 AM Well Name: SAN JUAN 32-8 UNIT Well Location: T31N / R8W / SEC 14 /

SWNW / 36.89952 / -107.651

County or Parish/State: SAN

JUAN / NM

Well Number: 303 Type of Well: INJECTION - ENHANCED Allottee or Tribe Name:

RECOVERY

Lease Number: NMSF079047 Unit or CA Name: Unit or CA Number:

US Well Number: 3004528703 Well Status: Water Injection Well Operator: HILCORP ENERGY

COMPANY

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: AMANDA WALKER Signed on: AUG 27, 2021 08:17 AM

Name: HILCORP ENERGY COMPANY

Title: Operations/Regulatory Technician

Street Address: 1111 TRAVIS ST.

City: HOUSTON State: TX

Phone: (346) 237-2177

Email address: mwalker@hilcorp.com

Field Representative

Representative Name:

Street Address:

City: State: Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: DAVE J MANKIEWICZ BLM POC Title: AFM-Minerals

BLM POC Phone: 5055647761 BLM POC Email Address: DMANKIEW@BLM.GOV

Disposition: Approved **Disposition Date:** 09/13/2021

Signature: Dave Mankiewicz

Page 2 of 2

San Juan 32-8 Unit 303 SWD 3004528703

Lease: NMSF079047

SR

7/19/2021: MIRU. CK WELL PRESSURES (TBG: 1400 PSI, CP: 710 PSI) BLED DWN TBG AND CSG TO 0#. ND WH. NU BOP. TST BOP TO 250 PSI LOW AND 2200 PSI HIGH. TST GOOD. SDFN.

7/20/2021: CK WELL PRESSURES (TBG: 310 PSI, CP: 160 PSI). ND STRIPPING HEAD & EQUL SPOOL. NU LUBRICATOR FOR PKR COVERAGE. SDFN.

7/21/2021: CK WELL PRESSURES (TBG: 110 PSI, CP: 80 PSI). BLW DWN WELL. ATTEMPTED TO RELEASE PKR. COULD NOT OPEN BY-PASS. RU PMP, PUT 1000 PSI ON CSG BY-PASS, OPENED, LET WELL EQUALIZE 1700 PSI ON WELL. POOH & LD 198 JTS 2 7/8" INJECTION STRING & PKR. SDFN.


7/22/2021: CK WELL PRESSURES (TBG: NA PSI, CP: 1750 PSI). RU BASIN WL W/CCL. RIH W/WL & BHA. SET PKR @ 8415'. PUH 3' RIH & TAG PKR. POOH W/SETTING TOOL & CCL. RD BASIN WL. ATTEMPTED TO BLEED OFF CSG, WOULD NOT BLEED DWN. SWI 1750 PSI ON WELL. RU BASIN WL W/DUMMY GUN & 10' WEIGHT BAR. RIH TO SET DEPTH @ 8415'. DID NOT TAG PKR. RIH TO 9224', FOUND PKR 14' BELOW BOTTOM PERF. POOH W/WL & WEIGHT BARS. SDWE.

7/26/2021: CK WELL PRESSURES (TBG: NA PSI, CP: 1750 PSI). RU BASIN WL & 30' LUBRICATOR. PU & RIH W/2 2/8" WL RE-ENTRY GUIDE. RIH TO 7780'. FLUSHED CSG W/110 BBLS FRESH H2O. SET PKR @ 8370' POOH W/CCL & SETTING TOOL, 450 PSI ON WELL. RD WL. 45 PSI ON CSG, BLED DWN & OBSERVE CSG FOR 30 MINS. SI CSG, RU PMP, PSI TST CSG & PKR TO 2000 PSI FOR 15 MINS, NO LEAK OFF, GOOD TST. SWI, SDFN.

7/28/2021: CK WELL PRESSURES (TBG: NA PSI, CP: 0 PSI). OBSERVE CSG FOR FLOW. FLOWING AFTER 45 MINS OF BEING OPEN. OBSERVED CSG FOR 45 MINS. SI CSG FOR 45 MINS, CK PSI, 0# ON CSG. SI CSG & MONITOR OVERNIGHT.

7/29/2021: CK WELL PRESSURES (TBG: NA PSI, CP: 0 PSI). PU RIH W/ 2 3/8" ON OFF TOOL, 2 3/8" 1.781 F NIPPLE 2 3/8" X 2 7/8" EUE XO 27 JT 2 7/8" 511 HYDRILL, 2 7/8" 511 X 2 7/8" XO, 237 JT 2 7/8" EUE IPC INJECTION STRING. CIRC 160 BBLS OF PKR FLUID. LATCHED ON PKR. PULLED 2 JTS. PKR HAS 10K COMPRESSION. SDFN.

7/30/2021: CK WELL PRESSURES (SITP 0 PSI, SICP 0 PSI, SIBHP 0 PSI). INSTALL REPLACEMENT TBG HANGER. LATCHED ONTO PKR & PULLED. SET DWN & LANDED HANGER INTO WH. 10K SET DWN ONTO PKR. ND BOP. NU WH. MIRU WELLCHECK. PT UNIT TO 640 PSI, GOOD TST. NMOCD INSPECTOR MONICA KUEHLING ONSITE TO WITNESS BH &MIT TESTS. WELLCHECK SERVICES CONDUCTED MIT ON 2 7/8" TBG & 4 ½", 5 ½" CSG ANNULUS ABV PKR TO 610 PSI FOR 30 MINS. RELEASED PRESSURE. BH & MIT TST PASSED. RDR WELLCHECK. MIRU EXPERT SLICKLINE. LOAD & PT LUBRICATOR TO 1900 PSI. TST GOOD. MADE 1 RUN W/1800 PSI ON LUBRICATOR. RUN #1 – 1.65" OD SPEAR & SPANG JARS ASSEMBLY TO PRESSURE DISKS @ 8393' SLM. KNOCKED OUT DISKS W/7 STROKES DWN. TBG PRESSURE DROPPED TO 1700 PSI. CONT DWN W/TOOLS THRU EOT. RDMO EXPERT SLICKLINE. FINISH NU WH SIDE CSG VALVES & DISPOSAL PLUMBING. WELL IS SI & SECURED. RDRR @ 1830 HRS.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 48018

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	48018
	Action Type:
	[C-103] Sub. Workover (C-103R)

CONDITIONS

Created By		Condition Date
mkuehling	None	1/25/2022