

Bc berry

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name		3 Bear		APL Number		30-025-41703	
Property Name		Burg SWD		Well No.		#1	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
I	35	20S	34E	16.20	S	304	E	Lea

Well Status

YES	TA'D WELL	NO	SHUT-IN	YES	INJ	INJECTOR	OIL	PRODUCER	GAS	DATE
										11-10-2021

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Cong	(E)Tubing
Pressure	0	0		0	1026
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Sign has wrong well #
showing #3
UL is I and not 1

Signature:	Kerry Mackey		OIL CONSERVATION DIVISION
Printed name:	Kerry Mackey		Entered into RBDMS
Title:	water tech		Re-test
E-mail Address:			
Date:	11-11-21	Phone:	
Witness:	Ray Johnson		

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 73287

CONDITIONS

Operator: 3BEAR FIELD SERVICES, LLC 1512 Larimer St, Suite 540 Denver, CO 80202	OGRID: 372603
	Action Number: 73287
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	2/10/2022