

Submit a Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-039-25219
5. Indicate Type of Lease STATE [] FEE [] FEDERAL - NMSF078774
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name ROSA UNIT
8. Well Number 315
9. OGRID Number 289408
10. Pool name or Wildcat BLANCO FRUITLAND COAL
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6549'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [x] Other
2. Name of Operator LOGOS OPERATING, LLC
3. Address of Operator 2010 AFTON PLACE, FARMINGTON, NM 87401
4. Well Location Unit Letter K : 2548 feet from the FSL line and 2066 feet from the FWL line
Section 30 31N Township 04W Range NMPM RIO ARRIBA County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6549'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: MIT [x]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

LOGOS Operating requests permission to perform an MIT on subject well per attached procedure and wellbore schematic.

Spud Date: []

Rig Release Date: []

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Etta Trujillo TITLE Regulatory Specialist DATE 3/15/2022

Type or print name Etta Trujillo E-mail address: etrujillo@logosresourcesllc.com PHONE: (505) 324-4154

For State Use Only

APPROVED BY: Monica Kuehling TITLE Deputy Oil and Gas Inspector DATE 4/8/2022

Conditions of Approval (if any):

Etta Trujillo

From: AFMSS <blm-afmss-notifications@blm.gov>
Sent: Monday, March 14, 2022 5:08 PM
To: Etta Trujillo
Subject: Well Name: ROSA UNIT, Well Number: 315, Notification of Issue with Notice Of Intent

The Bureau of Land Management

Notice of Issue with Notice Of Intent

- Operator Name: **LOGOS OPERATING LLC**
- Well Name: **ROSA UNIT**
- Well Number: **315**
- US Well Number: **300392521901S1**
- Sundry ID: **2661926**

The BLM received your Notice Of Intent, Mechanical Integrity Test on 03/14/2022. This is to notify you that we are returning your Notice Of Intent Mechanical Integrity Test for the following reason(s):

Prior approval not required. Please delete.

The returned Notice Of Intent has generated another task in your worklist that will allow you to update your request and then resubmit to the BLM.

You may contact the field office if you have any questions.

This notification is automatically generated. Please do not reply to this message as this account is not monitored.



MECHANICAL INTEGRITY TEST- (2022)

Rosa Unit 315
30-039-25219
2548' FSL & 2066' FWL
Sec 30, T31N, R04W
Rio Arriba County, New Mexico
Lat 36.8703003° Long -107.2974243°

PROJECT OBJECTIVE:

Top off the casing with packer fluid. Rig up chart recorder and conduct mechanical integrity test.

WORKOVER PROCEDURE:


1. Contact regulatory to ensure test has been scheduled with NMOCD.
2. Hold safety meeting. Comply with all LOGOS, BLM and NMOCD rules and regulations.
3. Top off the 5-1/2" casing with packer fluid at least 24 hours before the pressure test.
4. RU chart recorder to chart pressure test as follows:
 - **Top off with packer fluid, if needed.**
 - **Record pressure on 1 hour chart with 560 psig for 30 minutes with a 1000-pound spring.**
 - **Contact engineer with results of pressure test.**
5. Bleed off pressure.
6. Release chart recorder.



Wellbore Schematic

Well Name: Rosa Unit 315
 Location: Unit K, Sec 30, T31N, R04W 2548' FSL & 2066' FWL
 County: Rio Arriba
 API #: 30-039-25219
 Co-ordinates: Lat 36.8703003 Long -107.2974243
 Elevations: GROUND: 6549'
 KB: 6561'
 PBDT: 3523'
 TD: 3580'
 Depths (KB):

Last Updated: 4/15/2021 Moss
 Reviewed by: 3/11/2022 Peace
 Spud Date: 10/18/1992
 Completion Date: 9/6/1993
 Last Workover Date: 4/23/2015
 TA'd Well: 4/8/2017



Surface Casing: (10/18/1992)
 Drilled a 12-1/4" surface hole to 363'. Set 8-5/8", 24#, J-55 casing at 355'.

Abandoned Production Casing: (10/25/1992)
 Drilled a 7-7/8" production hole to 3500'. Set 5-1/2", 17#, J-55 casing at 3499'.
 Float collar at 3471'. DV tool at 2939'. Cmt lead w/ 25 sx 50/50 POZ (32cf) w/ 100sx Class B cmt (118 cf). Had to shut down for winter. TOC at 2400' (6/1993 CBL)
 (07/1993) Perf'd 3 sqz holes at 2500'. Sqz'd w/ 500 sx Halliburton Lite cmt & tailed w/ 100 sx Class B cmt. TOC at 1320' per 1999 CBL.
 (10/1999) Set a cmt retainer at 3270' and pumped 50 sx below & 50 sx above.

Sidetrack Production casing (10/1999)
 Cut 5-1/2" csg at 505' and pulled. Spotted 50 sx Class H cmt 300-545'. Tagged cmt at 327'.
 DO cmt & milled window 411'-437'. Drilled a 7-7/8" production hole to 3580'. Set 80 jts 5-1/2", 17#, N-80 csg at 3573' w/ DV tool at 3077'. Stage 1: cmt w/ 165 sx Class H cmt. Stage 2: cmt w/ 332 sx Type III, 35/65 POZ tailed by 50 sx Class H cmt. DO cmt to 3523'. TOC at 900' per 10/26/1999 CBL

Rods & Tubing:
 Pulled rods & tubing in 2017 to TA well

Pumping Unit:
 Churchill C-114-143-54 - not in use

Perforations:
 6/1993 - FC: 3296'-3301', 3350'-3352', 3356'-3364', 3370'-3376', 3379'-3384'.
 93, 0.5" holes. Acidized w/ 600 gal 7.5% HCL. Frac w/ 26,440# 40/70 sand & 201,000# 20/40 sand in 5,500 gal liner gel & 103,230 gal 25# Borate X-link gel.
 10/1999 - FC: 3302'-06', 3353'-58', 3361'-69', 3372'-78', 3383'-88'. 4spf, 112, 0.36" holes. Acidized 3353'-3388' w/ 900 gal 15% HCL & 3302'-3306' w/ 100 gal 15% HCL. Frac 3302'-3388' w/ 223,970# 12/20 Ottawa sand in 93,720 gal 20# Delta 140 frac fluid.

Formations:
 Ojo Alamo- 2770' Fruitland Coal- 3180'
 Kirtland- 2832' Pictured cliffs- 3425'

Additional Notes:
 (10/1992) Finished drilling & setting casing. Had to MOL due to winter closure.
 (09/1993) Completed well. Perf'd & frac'd FC formation. Perf'd csg at 2500' & sqzd w/ 600 sx cmt. CO to 3450' and landed 2-7/8" tubing at 3347'.
 (9/1995- 7/1998) well was SI due to economics, produced 7mcf/d & ~22 bwpd.
 (08/1998) PU install. Tag fill at 3437', did not CO. Land 2-7/8" tbg at 3423'. Ran 7/8" plain rods and a 2.5"x2"x14' RWAC pump.
 (09/1999) Drilled sidetrack, completed FC formation, CO to 3523. Landed 2-7/8" tbg at 3378'. Ran 7/8" plain rods and a 2.5"x2"x20' RWAC pump.
 (09/2004) Pull rods & pump. Tag fill at 3376'. CO to PBDT. EOT at 3424'. Added 3 sinker bars to rod config & ran a 2.5"x1.5"x20' RWAC pump.
 (04/2015) Pull rods & pump. Tag fill at 3504'. Pulled tbg, found leak in in collar on jt #101, just tightened collar. Land tbg at 3426'. Ran same rod configuration & same sized pump.
 (04/2017) Pulled rods & tbg. Ran csg scraper to 3312'. Attempted to set CIBP at 3240'. CIBP fell downhole, did not fish. Set new CIBP at 3240'. Loaded hole w/ 45 bbls fluid. Pressure tested to 590#, passed test.

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 96968

CONDITIONS

Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401	OGRID: 289408
	Action Number: 96968
	Action Type: [C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	Notify NMOCD 24 hours prior to MIT through phone and email - bradenhead test required prior to MIT -	4/8/2022