

Well Name: CHEVRON 12 FED	Well Location: T18S / R32E / SEC 12 / SWNE /	County or Parish/State: LEA / NM
Well Number: 05	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM40456	Unit or CA Name:	Unit or CA Number:
US Well Number: 3002530682	Well Status: Temporarily Abandoned	Operator: MATADOR PRODUCTION COMPANY

Subsequent Report

Sundry ID: 2667535

Type of Submission: Subsequent Report	Type of Action: Temporary Abandonment
Date Sundry Submitted: 04/19/2022	Time Sundry Submitted: 07:56
Date Operation Actually Began: 04/04/2022	

Actual Procedure: BLM Bond No.: NMB001079 Surety Bond No.: RLB0015172 • Notified BLM inspector 24 hrs prior to test. • Performed Bradenhead test (form attached) with BLM. • MIRU pump truck and pressure up on casing to 520 psi. • Record and chart MIT for 30 minutes (attached). • SWI & RDMO.

SR Attachments

Actual Procedure

- Chevron_12_Federal__5_Bradenhead_Test___MIT_4.4.22_20220419075555.pdf
- Chevron_12_Fed__5_WBD_3.31.22_20220419075545.pdf

SR Conditions of Approval

Specialist Review

TA_COA_20220602141146.pdf

Accepted for Record Only

SUBJECT TO LIKE APPROVAL BY BLM

K7

NMOCD 6/8/22

Received by OCD: 6/2/2022 2:34:11 PM

Page 2 of 12

Well Name: CHEVRON 12 FED	Well Location: T18S / R32E / SEC 12 / SWNE /	County or Parish/State: LEA / NM
Well Number: 05	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM40456	Unit or CA Name:	Unit or CA Number:
US Well Number: 3002530682	Well Status: Temporarily Abandoned	Operator: MATADOR PRODUCTION COMPANY

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: BRETT JENNINGS	Signed on: APR 19, 2022 07:55 AM
Name: MATADOR PRODUCTION COMPANY	
Title: Regulatory Analyst	
Street Address: 5400 LBJ FREEWAY, STE 1500	
City: DALLAS	State: TX
Phone: (972) 629-2160	
Email address: BRETT.JENNINGS@MATADORRESOURCES.COM	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: Jonathon W Shepard	BLM POC Title: Petroleum Engineer
BLM POC Phone: 5752345972	BLM POC Email Address: jshepard@blm.gov
Disposition: Approved	Disposition Date: 06/02/2022
Signature: Jonathon Shepard	

BLM Bond No.: NMB001079 Surety Bond No.: RLB0015172

- Notified BLM inspector 24 hrs prior to test.
- Performed Bradenhead test (form attached) with BLM.
- MIRU pump truck and pressure up on casing to 520 psi.
- Record and chart MIT for 30 minutes (attached).
- • SWI & RDMO.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6151 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Matador Resources</i>	API Number <i>30-025-30682</i>
Property Name <i>Chevron 12 Federal</i>	Well No. <i>#5</i>

1. Surface Location

UL - Lot <i>SWNE</i>	Section <i>12</i>	Township <i>18S</i>	Range <i>32E</i>	Feet from <i>1650</i>	N/S Line <i>FNL</i>	Feet from <i>1650</i>	E/W Line <i>FEL</i>	County <i>Lea</i>
-------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

G

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJ ☐	INJECTOR ☐	SWD ☐	PRODUCER ☒ OIL ☐	GAS ☐	DATE <i>4-4-2022</i>
--	--	---------------------------------	--------------------------------------	---------------------------------	--	---------------------------------	-------------------------

OBSERVED DATA


	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure <i>Ops</i>	<i>Ops</i>	NA	NA	<i>Ops</i>	TA
Flow Characteristics					
Puff	Y / ☒	Y / N	Y / N	Y / ☒	CO2
Steady Flow	Y / ☒	Y / N	Y / N	Y / ☒	WTR
Surges	Y / ☒	Y / N	Y / N	Y / ☒	GAS
Down to nothing	Y / ☒	Y / N	Y / N	Y / ☒	Type of Fluid
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	Label for
Water	Y / ☒	Y / N	Y / N	Y / ☒	Waterhead V

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.


Open surface valve no pressure, open casing, Loaded casing with 1 Bbl, Pressure casing up to 500 psi. Watched for 30 minutes, no leak off (good test). Bled pressure off. closed & secured well.

Signature: <i>JL</i>	OIL CONSERVATION DIVISION
Printed name: <i>Jose Perez / Jackson Driggs</i>	Entered into RBDMS
Title: <i>Consultant</i>	Re-test
E-mail Address: <i>jose23-perez@yahoo.com</i>	<i>K 7</i>
Date: <i>4-4-2022</i>	
Phone: <i>575-704-4884</i>	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM



Matador Resources
Chevron 12 Federal #5
Sec 12-T18S-R32E
Lea County, NM
API: 30-025-30682
CURRENT WELLBORE SCHEMATIC
Spud Date: 9/30/1989



Casing Information						
	Hole Size	Casing Size	Type	Weight lb/ft	Joints	Depth Set
Surface	17 1/2	13 3/8	unk	54.5#		350
Intermediate	12 1/4	8 5/8	unk	32# & 24#		2955
Production	7 7/8	5 1/2	unk	17#	223	9310

DV Tool
 Marker Jt.
 Float Collar

Cementing Record		
	# of Sx	TOC
Surface	375	Circ to surface
Intermediate	1450	Circ to surface
Production	1600	500'

Tubing - 2 3/8" J-55			Rods		Geologic Markers	
Item	Depth	#				
Joints					Rustler	1337
SN					Yates	2880
TAC					7 Rivers	3270
BP					Bowers	3768
PBTD					Queen	4046
Perfs	8132-9227		Pump		Penrose	4316
					Grayburg	4638
					BFSa	5066
					Delaware	5912
					Bone Spring	6560

Recent Workover History

Date	Details
3/4/2020	TA

Recent Recompletion History

Date	Depth	Details
2/2/2002	8132-8182	Frac w/ 24k gals 30# LF3C & 32k #'s 20-40 Econoprop

BLM Bond No.: NMB001079 Surety Bond No.: RLB0015172

- Notified BLM inspector 24 hrs prior to test.
- Performed Bradenhead test (form attached) with BLM.
- MIRU pump truck and pressure up on casing to 520 psi.
- Record and chart MIT for 30 minutes (attached).
- • SWI & RDMO.

District I
1633 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6151 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Matador Resources</i>		API Number <i>30-025-30682</i>	
Property Name <i>Chevron 12 Federal</i>		Well No. <i>#5</i>	

1. Surface Location

UL - Lot <i>SW 1/4</i>	Section <i>12</i>	Township <i>18S</i>	Range <i>32E</i>	Feet from <i>1650</i>	N/S Line <i>FNL</i>	Feet From <i>1650</i>	E/W Line <i>FEL</i>	County <i>Lea</i>
---------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

YES ☒	TA'D WELL	NO	YES ☒	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL ☒	PRODUCER	GAS	DATE <i>4-4-2022</i>
---	-----------	----	---	---------	----	-----	----------	-----	---	----------	-----	-------------------------

OBSERVED DATA


	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure <i>Ops</i>	<i>Ops</i>			<i>Ops</i>	
Flow Characteristics					
Puff	Y / ☒	Y / N	Y / N	Y / ☒	CO2 WTR GAS Type of fluid Injected for Waterflood & spikes
Steady Flow	Y / ☒	Y / N	Y / N	Y / ☒	
Surges	Y / ☒	Y / N	Y / N	Y / ☒	
Down to nothing	Y / ☒	Y / N	Y / N	Y / ☒	
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	
Water	Y / ☒	Y / N	Y / N	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.


Open surface valve no pressure, open casing, Loaded casing with 1 Bbl, Pressure casing up to 300 psi. Watched for 30 minutes, no leak off (goat test). Bled pressure off. closed & secured well.

Signature: <i>J. Perez</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Jose Perez / Jackson Driggs</i>		Entered into RBDMS	
Title: <i>Consultant</i>		Re-test	
E-mail Address: <i>jose23-perez@yahoo.com</i>			
Date: <i>4-4-2022</i>	Phone: <i>375-704-4880</i>		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM



Matador Resources
Chevron 12 Federal #5
Sec 12-T18S-R32E
Lea County, NM
API: 30-025-30682
CURRENT WELLBORE SCHEMATIC
Spud Date: 9/30/1989



Casing Information						
	Hole Size	Casing Size	Type	Weight lb/ft	Joints	Depth Set
Surface	17 1/2	13 3/8	unk	54.5#		350
Intermediate	12 1/4	8 5/8	unk	32# & 24#		2955
Production	7 7/8	5 1/2	unk	17#	223	9310

DV Tool
 Marker Jt.
 Float Collar

Cementing Record		
	# of Sx	TOC
Surface	375	Circ to surface
Intermediate	1450	Circ to surface
Production	1600	500'

Tubing - 2 3/8" J-55			Rods		Geologic Markers	
Item	Depth	#				
Joints					Rustler	1337
SN					Yates	2880
TAC					7 Rivers	3270
BP					Bowers	3768
PBTD					Queen	4046
Perfs	8132-9227				Penrose	4316
					Grayburg	4638
					BFSa	5066
					Delaware	5912
					Bone Spring	6560

Recent Workover History

Date	Details
3/4/2020	TA

Recent Recompletion History

Date	Depth	Details
2/2/2002	8132-8182	Frac w/ 24k gals 30# LF3C & 32k #'s 20-40 Econoprop

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 113193

COMMENTS

Operator: MATADOR PRODUCTION COMPANY One Lincoln Centre Dallas, TX 75240	OGRID: 228937
	Action Number: 113193
	Action Type: [C-103] Sub. Temporary Abandonment (C-103U)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	6/8/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 113193

CONDITIONS

Operator: MATADOR PRODUCTION COMPANY One Lincoln Centre Dallas, TX 75240	OGRID: 228937
	Action Number: 113193
	Action Type: [C-103] Sub. Temporary Abandonment (C-103U)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Like approval from BLM	6/8/2022