

BRADENHEAD TEST REPORT  
 OIL CONSERVATION DIVISION  
 HOBBS DISTRICT OFFICE

SAT 3  
 JMS

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

## BRADENHEAD TEST REPORT

|                                             |                                   |
|---------------------------------------------|-----------------------------------|
| Operator Name<br><b>Chevron USA Inc.</b>    | API Number<br><b>30-025-25731</b> |
| Property Name<br><b>CENTRAL VACUUM UNIT</b> | Well No.<br><b>83</b>             |

## Surface Location

|                      |                      |                        |                     |                          |                     |                          |                     |                      |
|----------------------|----------------------|------------------------|---------------------|--------------------------|---------------------|--------------------------|---------------------|----------------------|
| CL - Lot<br><b>J</b> | Section<br><b>36</b> | Township<br><b>17S</b> | Range<br><b>34E</b> | Feet from<br><b>1330</b> | NS Line<br><b>S</b> | Feet from<br><b>1330</b> | EW Line<br><b>E</b> | County<br><b>LEA</b> |
|----------------------|----------------------|------------------------|---------------------|--------------------------|---------------------|--------------------------|---------------------|----------------------|

## Well Status

|                         |                       |                        |                        |                          |
|-------------------------|-----------------------|------------------------|------------------------|--------------------------|
| TA'D Well<br><b>YES</b> | SHUT-IN<br><b>YES</b> | INJECTOR<br><b>YES</b> | PRODUCER<br><b>OIL</b> | DATE<br><b>21 Jun 21</b> |
|-------------------------|-----------------------|------------------------|------------------------|--------------------------|

## OBSERVED DATA

|                      | TA'Sect-Injection | Bottomhole | Choke/Well | Wellhead | Wellbore    |
|----------------------|-------------------|------------|------------|----------|-------------|
| Pressure             | <b>0</b>          | <b>0</b>   | <b>N/A</b> | <b>0</b> | <b>1700</b> |
| Flow Characteristics |                   |            |            |          |             |
| Puff                 | <b>0</b>          | <b>0</b>   | <b>0</b>   | <b>0</b> | <b>0</b>    |
| Steady Flow          | <b>0</b>          | <b>0</b>   | <b>0</b>   | <b>0</b> | <b>0</b>    |
| Surges               | <b>0</b>          | <b>0</b>   | <b>0</b>   | <b>0</b> | <b>0</b>    |
| Down to nothing      | <b>0</b>          | <b>0</b>   | <b>0</b>   | <b>0</b> | <b>0</b>    |
| Gas or Oil           | <b>0</b>          | <b>0</b>   | <b>0</b>   | <b>0</b> | <b>0</b>    |
| Water                | <b>0</b>          | <b>0</b>   | <b>0</b>   | <b>0</b> | <b>0</b>    |

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous fluid until applies.

|                                        |                           |
|----------------------------------------|---------------------------|
| Signature: <b>Van Riper</b>            | OIL CONSERVATION DIVISION |
| Printed name: <b>Van Riper Tyronne</b> | Entered into RBDMS        |
| Title: <b>FSA</b>                      | Re-test                   |
| Email Address: <b>HGAN@Chevron.com</b> |                           |
| Date: <b>21 Jun 21</b>                 | Phone                     |
|                                        | Witness                   |

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS  
  
Action 39141

CONDITIONS

|                                                                            |                                                            |
|----------------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>CHEVRON U S A INC<br>6301 Deauville Blvd<br>Midland, TX 79706 | OGRID:<br>4323                                             |
|                                                                            | Action Number:<br>39141                                    |
|                                                                            | Action Type:<br>[UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

|            |           |                |
|------------|-----------|----------------|
| Created By | Condition | Condition Date |
| gcordero   | None      | 6/13/2022      |