

Form 157-000-01-01 (Rev. 1-1-72)
 OCS Form 157-000-01-01 (Rev. 1-1-72)

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.	API Number 30-029-41343
Property Name CENTRAL VACUUM UNIT	Well No 170

Surface Location									
U.L. - Lot L	Section 36	Township 34N	Range 34E	Feet from 2490	N/S Line S	Feet From 500	E/W Line W	County LEA	

Well Status						DATE
TA'D Well YES	NO	SHUT-IN YES	NO	INJECTOR NO	PROD. CL. NO	2/ June 21

OBSERVED DATA

	(A)Surf. Intern	(B)Intercell	(C)Intern. M	(D)Test Casing	(E)Tubing
Pressure	0	0	N/A	0	1000
Flow Characteristics					
Pull	Y/O	Y/O	Y/N	Y/O	CO2
Steady Flow	Y/O	Y/O	Y/N	Y/O	WTR ☒
Surges	Y/O	Y/O	Y/N	Y/O	GLAS
Down to nothing	Y/O	Y/O	Y/N	Y/O	If applicable type
Gas or Oil	Y/O	Y/O	Y/N	Y/O	that entered the
Water	Y/O	Y/O	Y/N	Y/O	Water Based

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Van Riper</i>	OIL CONSERVATION DIVISION
Printed name: Van Riper Tyronne	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: HGAN@Chevron.com	
Date: 21 Jun 21	Phone
	Witness

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 39132

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 39132
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/13/2022