

District 1
 625 N. French Dr., Hobbs, NM 88240
 Phone: (505) 393-6161 Fax: (505) 393-9225

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

SAT 4

BRADENHEAD TEST REPORT

Operator Name Chevron USA INC.		API Number 30-025-02953	
Property Name CENTRAL VACUUM UNIT		Well No. 64	

Surface Location									
Bl. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
F	31	17S	35E	1980	N	1980	W	LEA	

Well Status						DATE	
TA'D Well	SHUT-IN	INJECTOR		PRODUCER			
YES	<input checked="" type="radio"/> NO	YES	<input checked="" type="radio"/> NO	INJ	SWD	<input checked="" type="radio"/> OIL GAS	17 Jun 21

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	0	0	N/A	190	240
Flow Characteristics					
Puff	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	CO2 _____
Steady Flow	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	WTR _____
Surges	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	GAS _____
Down to nothing	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	If applicable type
Gas or Oil	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	fluid injected for
Water	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Van Riper J</i>	OIL CONSERVATION DIVISION
Printed name: Van Riper, Tyrone Haan	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: <i>HAAN@Chevron.com</i>	
Date: <i>17 Jun 21</i>	Phone:
	Witness:

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 38711

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 38711
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/14/2022