

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Roughhouse Operating, LLC		API Number 30-025-31636	
Property Name Kemnitz South AFL State #001			Well No. 001

Surface Location

U/L - Lot O	Section 31	Township 16S	Range 34E	Feet from 660	N/S Line FSL	Feet From 1980	E/W Line FEL	County Lea
-----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D Well YES <input checked="" type="checkbox"/> NO	SHUT-IN YES <input checked="" type="checkbox"/> NO	INJECTOR INJ SWD	PRODUCER <input checked="" type="checkbox"/> OIL GAS	DATE 4/7/22
---	---	---------------------	---	-----------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	N/A	0 15	150
Flow Characteristics					
Puff	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	CO2 _____
Steady Flow	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	WTR _____
Surges	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	GAS _____
Down to nothing	<input checked="" type="checkbox"/> Y / N	<input checked="" type="checkbox"/> Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / N	fluid injected for
Water	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Gary Robinson JASON STARNOS		Entered RBDMS	
Title: Compliance Office		Re-test	
E-mail Address: Gary.Robinson@state.nm.us			
Date:	Phone: 575-263-4507		
	Witness:		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 98700

CONDITIONS

Operator: Roughhouse Operating, LLC 1605 Addison Road Addison, TX 75001	OGRID: 330608
	Action Number: 98700
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	6/27/2022