

Surface Reclamation Complete Report

Well Name: TERRY FU #001

API: 30-015-21810

Well Location: F-21-16S-25E

Surface Owner: W I JOHNSON

Reclamation Complete Date: 9/9/22


Total Acres reclaimed: 1.25

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Black Grama	2.0	4.0
	Blue Grama	2.0	4.0
"	Sideoats Grama	2.0	4.0
"	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
· ·	Little Bluestem	2.5	5.0
n n	Firewheel (Gaillardia)	1.0	2.0
"	Fourwing Saltbush	1.0	2.0
H H	Common Winterfat	0.5	1.0
Weights should be as pounds of pure live	seed.		


Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.



3rd party risers on NE side of pad







On-Site Regulat	ory Reclamation	Inspection	n		Date:		10 , 25, 2022			
Site Name:	Terry FU #001									
API Number:	30.0 15 . 2181	0 1	Plug Date:	12 , 07	, 2021		Program: Initial	Monitoring		
Trivamoer.	300		ring Date.				Final	Corrective	YES	NO
Was this the last remain	ing or only well on the lo	cation?								
	d pipelines that are going									_/
	equipment or structure (r				2n		re going to remain on lo rty risers on NE si		V	
If any production equipment	nent or structure (includi	ng 3rd party) i	s to remain o	on location, please spec	ify.	a pai	1, 11,501,501,112,51	oc or pad		
Site Evaluation										
Recontoured back to	original State/Topsoil	Replaced							YES	NO
ı	llar been filled and levele								_	
	ction holes been properly		reclaimed?							
	g materials have been rer	noved?								
All Facilities Removed	for Final Reclamation									
Have all of the pipelines			? (other than	the listed above)					V	
Has all of the required ju										
Have all of the required	anchors, dead men, tie di metal bolts and other ma				below ground level	?				
	rtable bases been remove		eenremoved	i e					-×	
Section Comments:										
Dry Hole Marker									YES	NO
Has a steel marker been	installed per COA require	ements?			Check	One:	☐ Burled 😿	Above Ground		
	I	Lease Name	& Number					Federal Lease #		
DHM Info	Operator Name	Court Hallic	a number	UL-S-T-R	Otr Section (Foot	tage)	API#	(Federal Only)		
Met Not Met						\rightarrow				
Free of Oil or Salt Con	taminated Soil								YES	NO
	s been remediated in con			d the terms of the Ope	rator's pit permit and	d closu	re plan?			
Have all other environm										
If any environmental cor	ocerns remain on the loca	ition, please sp	pecify							
Abandoned Pipelines										
Only need to provide ans				oned (in accordance wi	th 19. 15. 35. 10 NM	MC).			YES	NO
Have all fluids have been Have all abandoned pipe				rulated NORM . other ti	an that which accur	mulate	d under normal operation	202	\rightarrow	\leftarrow
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation? Have all accessible points of abandoned pipelines been permanently capped?					_					
Section Comments:										
Last Remaining or On		_								
Mease answer all question Have all electrical service	ons that apply in this grou			longer going to be any	well or facility remai	ining a	t this location.		YES	NO
	ility distribution infrastru			the location?						$\overline{}$
Have all the battery and					terms of the Opera	tor's p	it permit and dosure pla	in?		
	pipelines, production equ		removed fror	m the location?						
Has all the junk and trasl	h been removed from the	location?							V	
Section Comments: iEnvironmental Only-	Do not have to be met to	nass inspectio	VP.							
	with questions on the Re			in iEnvironmental but I	not related to NMOC	D form	15.		Met	Not Met
Free of Noxious or Invest										
Site Stability? Erosion co		ry) & working								
	tion? (Broadcast/Drilled) compared to background	Ω Met>75%.		Circle One:	0%	25%	50% 75%	100%		-/
Adequate Reclamation F									N	Ă
Section Comments:										
Additional Findings or	Comments	ire tracks f	ound fron	n west to east on	the south side	e of p	ad. Pipeline mar	kers by the risers	on the Ni	E side of
	Committee Co.						•	ohnnie on 10/26 o		
Inspector: Igor Rio	75							☐ READY FOR FAM		
Inspector: Igor Ric	-							☐ NEEDS FURTHER Inspection	n Result	
Picture Checklist:		Background		rd Party Equipment	Contamination	Π_{-}		PASS	$\overline{}$	AIL
	Site Comers M	Access Road	По	OG Equipment	M Trash/Junk	П_		- FASS	<u> </u>	
On-Site Inspection Fo	rm v1.xlsx									10/20/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 162088

DEFINITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162088
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

Is there any production equipment or structure (not including steel marker, poured

onsite concrete bases, or pipelines) that is going to remain on the location

If any production equipment or structure is to remain on the location, please

District I

specify

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV** 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 162088

QUESTIONS

	QUESTIONS		
Operator: EOG RESOURCES INC		OGRID: 7377	
		Action Number: 162088	
		Action Type: [C-103] Sub. Release After P&A (C-103Q)	
QUESTIONS			
Subsequent Report of: Location Ready For OCD Inspection After P&A			
Was this the last remaining or only well on the location	Yes		
Are there any abandoned pipelines that are going to remain on the location	No		

Yes

3rd party risers on NE side of pad. EOG reclaimed and restored pad including landowners

private road adjacent to the reclaimed pad (see attached map).

Site Evaluation Please answer all the questions in this group Have all the required pits been remediated in compliance with OCD rules and the Yes terms of the Operator's pit permit and closure plan Have the rat hole and cellar been filled and leveled Yes Have the cathodic protection holes been properly abandoned Yes Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground Yes level, been set in concrete THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT The (concrete-set) steel marker shows: LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE Must attach marker photograph(s). PERMANENTLY ENGRAVED INTO THE MARKER'S METAL Has the location been leveled as nearly as possible to original ground contour Yes Have all the required pipelines and other production equipment been cleared Yes Has all the required junk and trash been cleared from the location Yes Have all the required anchors, dead men, tie downs and risers have been cut off at Yes least two feet below ground level Have all the required metal bolts and other materials have been removed Yes Poured onsite concrete bases do not have to be removed. Have all the the required portable bases been removed Yes Have all other environmental concerns have been addressed as per OCD rules Yes If any environmental concerns remain on the location, please specify Not answered.

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

* Proof of the site marker (photograph) is required.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 162088

QUESTIONS	(continued)
QUESTIONS!	(COHUH IUCU)

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162088
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)
·	

QUESTIONS

Abandoned Pipelines			
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).			
Have all fluids have been removed from any abandoned pipelines	Not answered.		
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.		
Have all accessible points of abandoned pipelines been permanently capped	Not answered.		

Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location	Yes			
Is there any electrical utility distribution infrastructure that is remaining on the location	No			
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have all the retrievable pipelines, production equipment been removed from the location	Yes			
Has all the junk and trash been removed from the location	Yes			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 162088

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162088
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 162088

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162088
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	12/19/2022