

Surface Reclamation Complete Report

Well Name: ANDERSON CS STATE #002

API: 30-015-23961

Well Location: J-14-18S-24E

Surface Owner: YATES RANCH PROPERTY LLP

Reclamation Complete Date: 9/14/22

Total Acres reclaimed: 2.75

Seed Mix:

Mix	Species	lb/acre (Drilled)	Ib/acre (Broadcast)
4 Dinkus Ranch (8/13/2019)	Black Grama	3.0	6.0
II .	Blue Grama	2.5	5.0
II .	Hairy Grama	3.0	6.0
Ш	Sideoats Grama	4.5	9.0
"	Sacaton, Alkali	3.0	6.0
"	Saltbush Four-wing (DeWinged Seed)	2.0	4.0
"	Plains Bristlegrass	1.5	3.0

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





On-Site Regulate	ory Reclamation	Inspection		D:	ite:	10 / 0	3/ 2022			
Site Name:	Anderson CS Sta	ate #002								
	30.0 15 . 2396	1	07 . 20	2022						
API Number:	30.0 13 2360	Plug Date	e: <u>U/ / 28</u>	2022		Program:	Initial	Monitoring	wee	110
Was this the last remain	ing or only well on the los	cation?					Final	Corrective	YES	NO
	-	to remian on the location	n?							$\overline{}$
is there any production e	equipment or structure (r	not including steel market	, poured onsite concrete	e bases, or pipeli	ines) that a	re going to	remain on lo	cation?		
If any production equipm	nent or structure (includi	ng 3rd party) is to remain	on location, please spec	ify.						
Site Evaluation										
Recontoured back to	-	-							YES	NO
Have the cathodic protect		d? / abandoned & reclaimed	,						<u> </u>	
Rock or Caliche Surfacing										
Section Comments:									Ť	
All Facilities Removed	for Final Redamation	1								
		been deared? (other tha	n the listed above)							
Has all of the required ju			M 1 4 4 4	. h. l	13				<u> </u>	
		owns and risers have been sterials have been remove		t below ground i	eveir				- ×-	
Have all the required por									Ž	
Section Comments:										
Dry Hole Marker									YES	NO
Has a steel marker been	installed per COA require	ements?		a	heck One:	☐ Burle	d V	Above Ground		
		Lease Name & Number						Federal Lease #		
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Otr Section (Footage)	A	P1 #	(Federal Only)		
Met Not Met					-					
Free of Oil or Salt Con	taminated Soil								YES	NO
ı		npliance with OCD rules a	nd the terms of the Ope	rator's pit permi	t and closu	re plan?			$\overline{}$	
Have all other environment	ental concerns been addr	ressed as per OCD rules?							V	
If any environmental cor	cerrs remain on the loca	ition, please specify.								
Abandanad Birati										
Abandoned Pipelines	ware in this aroun if any	pipelines have been aban	donad fin necessaries wi	N 10 15 25 10	NMACI				YES	NO
Have all fluids have been			acries (in accordance w	07 13. 13. 33. 10	mmercy.					1
Have all abandoned pipe	lines been confirmed to	NOT contain additional re	gulated NORM, other ti	han that which a	ccumulate	d under no	rmal operation	on?		
Have all accessible point	s of abandoned pipelines	been permanently cappe	d?						_	
Section Comments:										
Last Remaining or On		<u>n</u> .p, specifically if there is n	a langue pales to be some	und or facility o	emoleles a	e elife formet	ine.		YES	NO
		moved from the location?		wen or juciney n	emaining o	E IIIIS IOCUE	OH.		7	NO
	•	cture that is remaining or								
		remediated in compliance		e terms of the O	perator's p	it permit ar	nd dosure pla	in?		
		ipment been removed fro	om the location?						<u> </u>	
Has all the junk and trash	i been removed from the	i location r							V	
Section Comments: iEnvironmental Only-	Do not have to be met to	nass inspertion								
		clamation Inspection For	n in iEnvironmental but I	not related to NA	MOCD form	s.			Met	Not Met
		or treatment in remarks								
Site Stability? Erosion co	ntrois in place (if necessa	ry) & working.								
Signs of seeding complet		O 14-1- 75-4	Grde One:		200	500	754	4000		
Revegetation Success as Adequate Reclamation F		17 Met > 75%.	Grose One:	0%	25%	50%	75%	100%	N	A
	manegr									
Section Comments:										
Additional Findings or	Comments:									
<u> </u>								TREADY FOR FA	N SUBMITTAL	
Inspector: Igor Rios Plantes					ER REVIEW					
Inspecti					on Result					
Picture Checklist:			3rd Party Equipment EOG Equipment	Contamination Trash/Junk	П-			PASS	O F/	AIL

On-Site_Inspection_Form v1.xlsx 10/20/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 158629

DEFINITIONS

Operator:		OGRID:
	EOG RESOURCES INC	7377
	P.O. Box 2267	Action Number:
	Midland, TX 79702	158629
		Action Type:
		[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 158629

QUESTIONS				
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID Action I	7377 Number: 158629 Type:		
CUITOTIONS		[C-103] Sub. Release After P&A (C-103Q)		
QUESTIONS Subsequent Report of: Location Ready For OCD Inspection After P&A				
Was this the last remaining or only well on the location	Yes			
Are there any abandoned pipelines that are going to remain on the location	No			
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	No			
If any production equipment or structure is to remain on the location, please specify	Not answered.			
lav = 1 u				
Site Evaluation				
Please answer all the questions in this group. Have all the required pits been remediated in compliance with OCD rules and the				
terms of the Operator's pit permit and closure plan	Yes			
Have the rat hole and cellar been filled and leveled	Yes			
Have the cathodic protection holes been properly abandoned	Yes			
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes			
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.			
Has the location been leveled as nearly as possible to original ground contour	Yes			
Have all the required pipelines and other production equipment been cleared	Yes			
Has all the required junk and trash been cleared from the location	Yes			
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes			
Have all the required metal bolts and other materials have been removed	Yes			
Poured onsite concrete bases do not have to be removed.				
Have all the the required portable bases been removed	Yes			
Have all other environmental concerns have been addressed as per OCD rules	Yes			
If any environmental concerns remain on the location, please specify	Not answered.			

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

* Proof of the site marker (photograph) is required.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 158629

QUESTIONS (continued)	
	OGRID: 7377
	Action Number:
	158629

Action Type: [C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Operator:

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location Yes				
Is there any electrical utility distribution infrastructure that is remaining on the location	No			
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have all the retrievable pipelines, production equipment been removed from the location	Yes			
Has all the junk and trash been removed from the location	Yes			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 158629

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	158629
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 158629

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	158629
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	11/18/2022