

# **Surface Reclamation Complete Report**

&

# **Annual Surface Reclamation Monitoring Report**

Well Name: GATES AAC #001

**API**: 30-015-24931

Well Location: C-22-18S-26E

**Surface Owner: WILSON WANDA FAYE ESTATE** 

**Reclamation Complete Date:** 4/28/21

**Reclamation Annual Monitoring Date**: 5/3/22


**Total Acres reclaimed:** .75

# **Seed Mix**:

Mix	Species	lb/acre (Drilled)	Ib/acre (Broadcast)
Wilson Ranch (5/9/2017)	Blue Grama	2.25	4.5
п	Little Bluestem	1.5	3.0
"	Plains Bristlegrass	1.5	3.0
"	Sideoats Grama	6.0	12.0

# Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





GRESHE REGULA	ory Reckar	nation dispe	etion		Dat	te:	<u> 11/09</u>	9/ <u>2022</u>	<u>'</u>		Page 3 oj
Site Name:	Gates AA	C #001									
API Number:	<sub>30-0</sub> 15	24931	Plug Date:	<u>05</u> <u>/</u> 19	<u>/ 2021</u>	Pi	rogram:	Initial Final	Monitoring Corrective	YES	NO
Was this the last remain	ning or only well	on the location?						Tilla	Corrective	123	110
Are there any abandone	,		ian on the location?							ĺ	$\overline{}$
Is there any production	equipment or s	tructure (not inclu	ıding steel marker, pour	ed onsite concrete	bases, or pipelin	es) that are	e going to	remain on lo	cation?		<b>V</b>
If any production equip	ment or structu	re (including 3rd p	party) is to remain on loc	cation, please speci	fy					_	
Site Evaluation											
Recontoured back to	original State	/Topsoil Replac	ed							YES	NO
Have the rat hole and co	ellar been filled	and leveled?								<b>✓</b>	
Have the cathodic prote			oned & reclaimed?							\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Rock or Caliche Surfacin	g materials hav	e been removed?									
Section Comments: All Facilities Remove	d for Final Rec	lamation								_	
			eared? (other than the I	listed above)							
Has all of the required j	•		·							<del>                                   </del>	
Have all of the required	anchors, dead i	men, tie downs an	d risers have been cut o	off at least two feet	below ground le	vel?				<u> </u>	
Have all of the required	metal bolts and	l other materials h	nave been removed?							<b>/</b>	
Have all the required po	ortable bases be	en removed?								$\checkmark$	
Section Comments:										_	
Dry Hole Marker										YES	NO
Has a steel marker been	installed per C	OA requirements?	1		Che	eck One:	☐ Burie	d 🚺	Above Ground	<b>✓</b>	
		Lease	Name & Number						Federal Lease #		
DHM Info	Operator	Name		UL-S-T-R	Qtr Section (F	ootage)	Al	PI #	(Federal Only)		
Me Not Me								/			
Free of Oil or Salt Co		l oil							l	YES	NO
Have all the required pi	ts been remedia	ited in compliance	with OCD rules and the	terms of the Oper	ator's pit permit	and closure	e plan?				
Have all other environm	nental concerns	been addressed a	s per OCD rules?							<b>✓</b>	
If any environmental co	ncerns remain o	on the location, pl	ease specify.							_	
Abandoned Pipelines	1										
			es have been abandoned	(in accordance wit	h 19. 15. 35. 10 N	VMAC).				YES	NO
Have all fluids have bee Have all abandoned pip			oipeiines? ntain additional regulate	ed NORM , other th	an that which ac	cumulated	under nor	rmal operatio	on?		lacksquare
Have all accessible poin				,							
Section Comments:		ppp	, , ,								
Last Remaining or Or	ly Well on the	Location									
Please answer all questi	ons that apply i	n this group, speci	fically if there is no long	er going to be any	well or facility rei	maining at	this locati	on.		YES	NO
Have all electrical service	e poles and line	es been removed f	rom the location?							<b>✓</b>	
			at is remaining on the lo							<u> </u>	
			ated in compliance with been removed from the		terms of the Op	erator's pit	permit ar	id closure pla	an?	<del>/</del>	
Has all the junk and tras				: location:						<del>\</del>	
Section Comments:										·	
iEnvironmental Only-	Do not have to	be met to pass in:	spection								
This section corresponds	s with questions	on the Reclamati	on Inspection Form in iEi	nvironmental but n	ot related to NM	OCD forms				Met	Not Met
Free of Noxious or Invas	sive Weeds? (No	ote species or trea	tment in remarks)							<b>✓</b>	
Site Stability? Erosion co			orking.							<u> </u>	
Signs of seeding comple			750/	Ciarla On a	00/	250/	F.00/	750/	100%		<del>                                     </del>
Revegetation Success as Adequate Reclamation			>/5%.	Circle One:	0%	25%	50%	75%	100%	N	A
	ence mstaneu:									11	, , ,
Section Comments:		Dower	nolog are not pro	oont on locati						_	
Additional Findings o	r Comments:	Power	poles are not pres	Sent on location	JII						
										A N. C	
Inspector: Igor Ric	os								☐ READY FOR F. ☐ NEEDS FURTH		
-										tion Result	
Picture Checklist:	DHM	<b>⊠</b> Backgrou		, , ,	Contamination	₫			PASS	○ F	AIL
	Site Corners	Access R	oad EOG Eq	quipment	Trash/Junk	□					

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

DEFINITIONS

Action 162746

#### **DEFINITIONS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162746
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

### **DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 162746

Q	UESTIONS
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377 Action Number: 162746 Action Type:
	[C-103] Sub. Release After P&A (C-103Q)
QUESTIONS	
Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	No
If any production equipment or structure is to remain on the location, please specify	Not answered.
Site Evaluation	
Please answer all the questions in this group.	
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes
The (concrete-set) steel marker shows:  Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	Yes
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	Yes
Poured onsite concrete bases do not have to be removed.	
Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.

\* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS, Page 2

Action 162746

QUESTIONS	(continued)
QUESTIONS:	COHUHUCU <i>i</i>

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162746
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

#### QUESTIONS

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location	Yes			
Is there any electrical utility distribution infrastructure that is remaining on the location	Yes			
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have all the retrievable pipelines, production equipment been removed from the location	Yes			
Has all the junk and trash been removed from the location	Yes			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

ACKNOWLEDGMENTS

Action 162746

### **ACKNOWLEDGMENTS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162746
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

### **ACKNOWLEDGMENTS**

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 162746

## **CONDITIONS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	162746
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

### CONDITIONS

Created By		Condition Date
gcordero	None	12/2/2022