

Surface Reclamation Complete Report

Well Name: RICHARD KNOB AEX STATE #001

API: 30-015-25848

Well Location: G-34-17S-24E

Surface Owner: STATE OF NEW MEXICO

Reclamation Complete Date: 5/19/22

Total Acres reclaimed: 2.75 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)	
NMSLO - Loamy (L)	Black Grama	2.0	4.0	
n .	Blue Grama	2.0	4.0	
п	Sideoats Grama	2.0	4.0	
п	Sand Dropseed	1.0	2.0	
п	Alkali Sacaton	2.5	5.0	
п	Little Bluestem	2.5	5.0	
Weights should be as pounds of pure live seed.				

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

Durango riser on NE and NW side of pad.







On-Site Regulato	ory Reclamation	Inspection				Date:	11/0	8/ 2022	2		
Site Name:	Richard Knob Al	EX State #001									
API Number:	₃₀₋₀ 15 . 2584	48 Plug	Date:	11 / 04	4 / 2021		Program:		Monitoring		
Was this the last remaining	ng or only well on the lo	cation?						Final	Corrective	YES	NO
Are there any abandoned			cation?								
Is there any production e				onsite concrete	bases, or pip	elines) that a	are going to	remain on lo	cation?	_/	
If any production equipm	ent or structure (includi	ing 3rd party) is to re	emain on locati	ion, please spec	ify.	3rd pa	rty riser	on NE sid	le and NW side		
of pad.											
Site Evaluation											
Recontoured back to o	original State/Topsoil	Replaced								YES	NO
Have the rat hole and cel										/	
Have the cathodic protect			imed?								
Rock or Calidhe Surfacing	materials have been re	moved?									
Section Comments:											
All Facilities Removed Have all of the pipelines 8			er than the liste	ed above)						_/	
Has all of the required jur				ou accesy						- V	
Have all of the required a	inchors, dead men, tie d	owns and risers hav	e been cut off a	at least two feet	t below groun	d level?				V	
Have all of the required n			moved?							_	
Have all the required por	table bases been remov	ed?								V	
Section Comments:											
Dry Hole Marker										YES	NO
Has a steel marker been i	nstalled per COA requir	ements?				Check One:	Burie	rd 💆	Above Ground		
		Lease Name & Nu	mber						Federal Lease #		
DHM Info Met	Operator Name			UL-S-T-R		(Footage)	A	P1#	(Federal Only)		
Not Met		_ ·	_	<u> </u>	<u> </u>	/					
Free of Oil or Salt Cont	taminated Soil									YES	NO
Have all the required pits	been remediated in cor	mpliance with OCD r	ules and the te	rms of the Oper	rator's pit per	mit and clos	ure plan?			_	
Have all other environmental concerns been addressed as per OCD rules?					✓						
If any environmental con	cerns remain on the loca	ation, please specify									
Abandoned Pipelines											
Only need to provide answ	wers in this group, if any	pipelines have been	abandoned (in	accordance wit	th 19. 15. 35.	10 NMAC).				YES	NO
Have all fluids have been										_	/
Have all abandoned pipel				NORM , other th	nan that which	h accumulate	ed under no	rmal operation	on?	-	
Have all accessible points	of abandoned pipelines	been permanently	capped?								-
Section Comments:											
Last Remaining or Only Please answer all question		_	en le no longue e	nales to be serve	well or facility	u casa alala a	at this lases	i an		YES	NO
Have all electrical service				going to be any	wer or judini	y remaining i	ot tras rocut	ion.		J/	NO
Is there any electrical util				tion?						_ `	
Have all the battery and p	pit location(s) have been	remediated in com	pliance with O	CD rules and the	e terms of the	Operator's	pit permit a	nd dosure pla	in?		
Have all the retrievable p			red from the lo	cation?							
Has all the junk and trash	been removed from the	e location?									
Section Comments: iEnvironmental Only- Do not have to be met to pass inspection											
This section corresponds	with questions on the Re	clamation Inspectio	n Form in iEnvir	ronmental but r	not related to	NMOCD for	NS.			Met	Not Met
Free of Noxious or Invasion			narks)								
Site Stability? Erosion cor Signs of seeding completi										<u> </u>	
Revegetation Success as				Cirde One:	0%	25%	509	75%	100%		-
Adequate Reclamation Fe							-			<i></i>	Ť
Section Comments:											
Additional Findings or	Comments:										
									READY FOR FAI	V SURMITTAL	
Inspector: Igor Rio	5			_					NEEDS FURTHE		
Picture Checklist:	₹DHM M	Background	M 3rd Party E	Equipment	Contaminat	ion П_					
		Access Road	EOG Equip		Trush/Junk	П_			PASS	U #	AIL .

On-Site_Inspection_Form v1.xlsx 10/20/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 157700

DEFINITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	157700
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 157700

Q	UESTIONS
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID:
QUESTIONS	[0-103] Sub. Nelease Allel F &A (0-1034)
Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes
If any production equipment or structure is to remain on the location, please specify	3rd party riser on NE side and NW side.
Site Evaluation	
Please answer all the questions in this group.	
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	Yes
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	Yes
Poured onsite concrete bases do not have to be removed.	
Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.
* Proof of the site marker (photograph) is required.	

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 157700

QUESTIONS (continued)

OGRID:
7377
Action Number:
157700
Action Type:
[C-103] Sub. Release After P&A (C-103Q)
Αc

QUESTIONS

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location	Yes			
Is there any electrical utility distribution infrastructure that is remaining on the location	No			
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have all the retrievable pipelines, production equipment been removed from the location	Yes			
Has all the junk and trash been removed from the location	Yes			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 157700

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	157700
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 157700

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	157700
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	12/19/2022