

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: BELL LAKE UNIT Well Location: T22S / R34E / SEC 32 / County or Parish/State: LEA /

SWNW /

NM

Well Number: 21 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: STATE Unit or CA Name: BELL LAKE, BELL Unit or CA Number:

LAKE INT. MORROW B

NMNM68292F, NMNM68292X

US Well Number: 3002535118 Well Status: Abandoned Operator: KAISER FRANCIS OIL

COMPANY

## **Subsequent Report**

**Sundry ID: 2698244** 

Type of Submission: Subsequent Report

Type of Action: Plug and Abandonment

Date Sundry Submitted: 10/14/2022 Time Sundry Submitted: 02:12

**Date Operation Actually Began:** 09/29/2022

**Actual Procedure:** 9/29/22: POOH w/ tubing. Set CIBP @ 11,150' 9/30/22: TIH tag plug @ 11,150'. Spot 180 bbls mud. Spot 25sx on plug. 10/3/22: Tag TOC @ 10,976'. Pump 140 bbls mud. Spot 50sx @ 8526'. WOC. 10/4/22: Tag TOC @ 8230'. Set CIBP @ 7693'. Run CBL on 7" f/ 7000'-400'. TOC est @ ~3380' 10/5/22: Spot 25sx on top of CIBP. WOC and tag @ 7537'. Spot 40sx @ 6826. WOC and did not tag plug. Spot 40 additional sx @ 6826'. 10/6/22: Tag TOC @ 6549'. Test 7" to 500#. Spot 35sx @ 5290'. WOC and tag @ 5088'. Spot 45sx @ 3700'. WOC and tag @ 3477' 10/10/22: Run freepoint. Cut and pull 7" casing f/ 2600'. 10/11/22: Spot 80sx @ 2650'. WOC & tag @ 2417'. 10/12/22: Run CBL on 9 5/8". TOC @ surface. Spot 70sx 2263'. Spot 70sx @ 1650'. Spot 70sx @ 880'. Circ cement f/ 100' to surface. Well plugged.

## **SR Attachments**

### **Actual Procedure**

Log\_belllake21\_20221014141142.pdf

NBLU\_21\_Plugging\_Email\_20221014141142.pdf

NBLU\_21\_Plugging\_Email\_2\_20221014141142.pdf

Bell\_Lake\_North\_21\_P\_A\_WBD\_20221014141116.pdf

Accepted for record – NMOCD

JRH 05/03/2023

eceived by OCD: 12/20/2022 8:22:57 AM
Well Name: BELL LAKE UNIT

Well Location: T22S / R34E / SEC 32 /

SWNW /

County or Parish/State: LEA?

NM

Well Number: 21

Type of Well: CONVENTIONAL GAS

**Allottee or Tribe Name:** 

Lease Number: STATE Unit or CA Name: BELL LAKE, BELL **Unit or CA Number:** 

LAKE INT. MORROW B

NMNM68292F, NMNM68292X

**US Well Number: 3002535118** Well Status: Abandoned Operator: KAISER FRANCIS OIL

COMPANY

## **Operator**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Signed on: OCT 14, 2022 02:12 PM **Operator Electronic Signature: CHRISTINA OPFER** 

Name: KAISER FRANCIS OIL COMPANY

Title: Regulatory Manager

Street Address: 6733 S YALE AVENUE

City: TULSA State: OK

Phone: (918) 491-4468

Email address: CHRISTINAO@KFOC.NET

## **Field**

**Representative Name:** 

**Street Address:** 

City: State: Zip:

Phone:

**Email address:** 

## **BLM Point of Contact**

**BLM POC Name: JAMES A AMOS BLM POC Title:** Acting Assistant Field Manager

**BLM POC Phone:** 5752345927 BLM POC Email Address: jamos@blm.gov

**Disposition:** Accepted **Disposition Date:** 12/20/2022

Signature: James A. Amos

Page 2 of 2

#### Kaiser-Francis Oil Company North Bell Lake 21 Location: Section 32-22S-34E API: 30-025-35118 Field: OJO Chiso County: Spud Date: Lea 08/29/00 State: **New Mexico** Completed: 12/00 Elevation: KB - 3448' GL - 3431' **Diagram Updated:** 3/25/2020 Work History: 8/00- Drilled by DVN to 13,407'. Got stuck @ 5239' and had to run 9 5/8" to cover sloughling hole. Some deviation shallow: 3.5 @ 2357, 4 @ 2768, 2.25 @ 20", 94# K-55 @ 830'. Cmt'd w/ 1025 3081', 2.75 @ 4270', 2.5 @ 5104. Pretty mild dev from there to TD. sx. Circ. 8/00- Ran 4 1/2" liner. Cemented and csg wouldn't bleed off. Found drill string to be plugged. C/O w/ CT. C/O cement to liner top. Pos test to 1500#, neg test 2325# and held. RIH and set ZXP liner top packer w/ tieback seal. Set pkr @ 11,655'. C/O to 13,366' w/ 3 3/4" mill. 13 3/8", 61# J-55 ST&C @ 2213'. Cmt'd w/ 1300 sx. Circ. **12/00-** TIH w/ TCP guns and <u>TCP'd Morrow 12,886-90, 12,900-06, 12,915-16,</u> 13,063-72, 13,080-82, 13,092-94 6 SPF (144 holes). Well IP'd 2.8 MMcf/d, 34 BOPD flowing at 5700# FTP on 6/64" ck. CAOF 30,877 mcf/d 2/05-Az Morrow w/ 204 gal acetic acid, 2496 gal methanol, 300 gal MS-16 and 5 tons CO2 + 100 BS, MP-6417#, AR-5.1, ISIP-3219, 15-241# 9 5/8" 40# N80 & K55 @ 5239'. Cmt'd w/ 625 sx. 8/08-Set CIBP @ 12,865'. Dump 35' cmt. Perf Wolfcamp 11,201-07' w/ 4" csg gun @ 3 SPF. Ran tubing and packer and frac'd Wolfcamp 11,201-07 down 2 3/8" tubing w/ 1000 gal acid, 456 bbls X-link & 15,645# 18/40 Versaprop. AR-9.1, AP-8500. ISIP-6172 15-4613 IP'd 22 BOPD + 35 Mcf/d Tubing Detail ( string landed w/ 13K tension) 11/08-Set RBP @ 8,390'. Perf Delaware 7801-7798, 7758-50, 7743-46 @ 2 349 jts 2 3/8" L-80 (some AB Mod) SPF. Frac 7743-7801' OA down 7" csg w/ 75 bbls 7.5% HCl, 2038 bbls Spectra Frac carrying 83000# 20/40 white and 21000# 16/30 Siberprop. AP-1418, AR-2 3/8" X 7" TAC @ 11,100' 41.3. IP'd 8.3 BOPD and 128 BWPD (load) 4 jts 2 3/8" 1 25/32" Mech SN @ 11,230' 2/09-Commingled Wolfcamp and Delaware. Noted box wear on top rods. 2 3/8" X 4' perf sub 7/09-Box break 3rd rod from surface. 2/11-PC. Stuck w/ scale. Barrell pitted. 1 jt 2 3/8" MA EOT @ 11,265' 3/11-PC pump stuck open w/ scale 5/11-Rods back off (plunger broken) 8/11-Body break 4th rod from surface. DV Tool @ 6771'. Cmt'd w/ 1025 sx 1/12-TL. Scanned: 299 yellow, 30 blue, 23 green, hole above SN 2/12-TL. Hydrotested all its to 7000#. No leaks found **Delaware:** 7743-7801' OA 11/12-PC. Barrel grooved and scored. Scale in pump. 3/13-TL. Scanned: all yellow. Hole above SN. 4/15-Box break between 3rd and 4th rod. Ran grooved plunger pump. No scale Rod Detail found in pump. Installed guides on top 125 rods. 125 7/8" N97 rods w/ S/O guides 41 7/8" N97 rods 7/18- Scanned 298-Y, 36-B, 14-G, 5-R. No Hole. Replaced 20 jts. 240 3/4" N97 rods 42 7/8" N97 rods On/off tool Spiral rod guide 2" X 1.25" X 24 RHBM w/ grvd plgr Wolfcamp: 11,201-07' ZXP Liner top packer @ 11,655' 7" 26# P-110 csg @ 12,020'. Cmt'd w/ 925 CIBP @ 12,865' w/ 35' cmt on top Morrow: 12,886-13,094' OA 4-1/2" 13.5# P-110 liner 11,674-13,407'. Cmt'd w/ 200 sx. PBTD - 13,366 \*Good Porosity @ 10,530'. Decent porosity in BS @ 10,200'. Same Below 10.050 TD - 13,407

# **Kaiser-Francis Oil Company**


Location: Section 32-22S-34E

Field: OJO Chiso

County: Lea

State: New Mexico

**Elevation:** KB - 3448' GL - 3431'



## North Bell Lake 21 (P&A)

**API:** 30-025-35118

 Spud Date:
 08/29/00

 Completed:
 12/00

 Diagram Updated:
 11/19/2021

## Work History:

**8/00-** Drilled by DVN to 13,407'. Got stuck @ 5239' and had to run 9 5/8" to cover sloughling hole. Some deviation shallow: 3.5 @ 2357, 4 @ 2768, 2.25 @ 3081', 2.75 @ 4270', 2.5 @ 5104. Pretty mild dev from there to TD.

**8/00-** Ran 4 1/2" liner. Cemented and csg wouldn't bleed off. Found drill string to be plugged. C/O w/ CT. C/O cement to liner top. Pos test to 1500#, neg test 2325# and held. RIH and set ZXP liner top packer w/ tieback seal. Set pkr @ 11,655'. C/O to 13,366' w/ 3 3/4" mill.

**12/00-** TIH w/ TCP guns and <u>TCP'd Morrow 12,886-90, 12,900-06, 12,915-16, 13,063-72, 13,080-82, 13,092-94 6 SPF (144 holes). Well IP'd 2.8 MMcf/d, 34 BOPD flowing at 5700# FTP on 6/64" ck. CAOF 30,877 mcf/d</u>

**2/05**-Az Morrow w/ 204 gal acetic acid, 2496 gal methanol, 300 gal MS-16 and 5 tons CO2 + 100 BS. MP-6417#, AR-5.1. ISIP-3219, 15-241#

**8/08**-Set CIBP @ 12,865'. Dump 35' cmt. Perf Wolfcamp 11,201-07' w/ 4" csg gun @ 3 SPF. Ran tubing and packer and frac'd Wolfcamp 11,201-07 down 2 3/8" tubing w/ 1000 gal acid, 456 bbls X-link & 15,645# 18/40 Versaprop. AR-9.1, AP-8500. ISIP-6172 15-4613 **IP'd 22 BOPD + 35 Mcf/d** 

**11/08**-Set RBP @ 8,390'. Perf Delaware 7801-7798, 7758-50, 7743-46 @ 2 SPF. Frac 7743-7801' OA down 7" csg w/ 75 bbls 7.5% HCl, 2038 bbls Spectra Frac carrying 83000# 20/40 white and 21000# 16/30 Siberprop. AP-1418, AR-41.3. **IP'd 8.3 BOPD and 128 BWPD (load)** 

2/09-Commingled Wolfcamp and Delaware. Noted box wear on top rods.
7/09-Box break 3rd rod from surface. 2/11-PC. Stuck w/ scale. Barrell pitted.
3/11-PC pump stuck open w/ scale 5/11-Rods back off (plunger broken)
8/11-Body break 4th rod from surface.

**1/12-**TL. Scanned: 299 yellow, 30 blue, 23 green, hole above SN **2/12-**TL. Hydrotested all jts to 7000#. No leaks found

**11/12-**PC. Barrel grooved and scored. Scale in pump. **3/13-**TL. Scanned: all yellow. Hole above SN.

**4/15**-Box break between 3rd and 4th rod. Ran grooved plunger pump. No scale found in pump. Installed guides on top 125 rods.

**7/18-** Scanned 298-Y, 36-B, 14-G, 5-R. No Hole. Replaced 20 jts. **1/21-**Frac protect well: LD rods. Scan tubing OOH. RIH w/ packer. **10/22-**Well P&A'd

76'

<sup>\*</sup>Good Porosity @ 10,530'. Decent porosity in BS @ 10,200'. Same Below 10,050'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 168703

**CONDITIONS** 

Operator:	OGRID:	
KAISER-FRANCIS OIL CO	12361	
PO Box 21468	Action Number:	
Tulsa, OK 74121146	168703	
	Action Type:	
	[C-103] Sub. Plugging (C-103P)	

#### CONDITIONS

Created By		Condition Date
john.harrisor	None	5/3/2023