

BRADENHEAD TEST REPORT

Operator Name <i>Matador</i>				API Number <i>30-025-29047</i>			
Property Name <i>Young Deep Unit</i>				Well No. <i>#16</i>			
1. Surface Location							
UL - Lot <i>E</i>	Section <i>9</i>	Township <i>18S</i>	Range <i>32E</i>	Feet from <i>1980</i>	NS Line <i>FNL</i>	Feet from <i>660</i>	EW Line <i>FNL</i>
							County <i>Lea</i>
Well Status							
☒ YES	TAID WELL		☒ YES	SHUT-IN		☒ YES	INJECTOR
NO		NO		NO		SWD	
						OIL	
						PRODUCER	
						GAS	
							DATE <i>8-16-2022</i>

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	<i>0</i>	<i>N/A</i>	<i>N/A</i>	<i>0</i>	<i>0</i>
Flow Characteristics					
Puff	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Type of fluid
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Delayed for
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Wearhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Jose Perez</i>		Entered into RBDMS	
Title: <i>Consultant</i>		Re-test	
E-mail Address: <i>jose23.perez@jahoo.com</i>			
Date: <i>8-16-2022</i>	Phone: <i>575-704-4554</i>		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

LK

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 136839

CONDITIONS

Operator: MATADOR PRODUCTION COMPANY One Lincoln Centre Dallas, TX 75240	OGRID: 228937
	Action Number: 136839
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	7/28/2023