

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

# BRADENHEAD TEST REPORT

|                                           |               |                 |              |                  |                            |                   |                 |                     |  |
|-------------------------------------------|---------------|-----------------|--------------|------------------|----------------------------|-------------------|-----------------|---------------------|--|
| BRADENHEAD TEST REPORT                    |               |                 |              |                  |                            |                   |                 |                     |  |
| Operator Name<br>CROSS TIMBER ENERGY, LLC |               |                 |              |                  | API Number<br>30-025-28821 |                   |                 |                     |  |
| Property Name<br>NORTH VACUUM UNIT        |               |                 |              |                  | Well No<br>260             |                   |                 |                     |  |
| 1. Surface Location                       |               |                 |              |                  |                            |                   |                 |                     |  |
| Di. - Lat<br>C                            | Section<br>13 | Township<br>17S | Range<br>34E | Feet from<br>660 | NS Line<br>FSL             | Feet From<br>2080 | ESW Line<br>FWL | County<br>LEA       |  |
| Well Status                               |               |                 |              |                  |                            |                   |                 |                     |  |
| PAID WELL<br>YES                          |               | (NO)            |              | SHUT-IN<br>YES   |                            | (NO)              |                 | INJ INJECTOR<br>SWD |  |
|                                           |               |                 |              |                  |                            | (OIL)             |                 | PRODUCER<br>GAS     |  |
| DATE<br>8-21-23                           |               |                 |              |                  |                            |                   |                 |                     |  |

OBSERVED DATA

| OBSERVED DATA        |             |              |              |              |               |
|----------------------|-------------|--------------|--------------|--------------|---------------|
|                      | (A) Surface | (B) Intermed | (C) Intermed | (D) Prod Cng | (E) Tubing    |
| Pressure             | 0           | N/A          | N/A          | 40           | 0             |
| Flow Characteristics |             |              |              |              |               |
| Puff                 | Y/N         | Y/N          | Y/N          | Y/N          | CO2           |
| Steady Flow          | Y/N         | Y/N          | Y/N          | Y/N          | WTR           |
| Surges               | Y/N         | Y/N          | Y/N          | Y/N          | GAS           |
| Down to nothing      | Y/N         | Y/N          | Y/N          | Y/N          | Type of State |
| Gas or Oil           | Y/N         | Y/N          | Y/N          | Y/N          | Isolvent for  |
| Water                | Y/N         | Y/N          | Y/N          | Y/N          | Waterflood it |
|                      |             |              |              |              | concs         |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well Down Rod Art

|                                              |                           |
|----------------------------------------------|---------------------------|
| Signature <i>[Signature]</i>                 | OIL CONSERVATION DIVISION |
| Printed name Roy Candillo                    | Entered into RBDMS        |
| Title Lease Operator                         | Re-test                   |
| E-mail Address RCandillo@ctfieldservices.com |                           |
| Date 8-31-23                                 |                           |
| Phone 575-659-9866                           |                           |
| Witness                                      |                           |

INSTRUCTIONS ON BACK OF THIS FORM

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 286453

CONDITIONS

|                                                                                       |                                                            |
|---------------------------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>CROSS TIMBERS ENERGY, LLC<br>400 West 7th Street<br>Fort Worth, TX 76102 | OGRID:<br>298299                                           |
|                                                                                       | Action Number:<br>286453                                   |
|                                                                                       | Action Type:<br>[UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| kfortner   | None      | 11/28/2023     |