DATE 5/14/24 **SIGNATURE** Type or print name PHONE: For State Use Only DATE 5/24/24 TITLE Compliance Officer A

Released to Imaging: 5/24/2024 10:55:47 AM

## Sagebrush #001H

## Pump Repair Procedure

Spot and rig up on well. NU BOP.

TOOH w/rods and pump.

Unset TAC and POOH w/tubing.

RIH w/tubing and pressure test.

RIH w/pump and rods.

Confirm pump action and ND BOP. Move off well.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 344283

## **CONDITIONS**

| Operator:                     | OGRID:                         |
|-------------------------------|--------------------------------|
| Unitex Oil & Gas, L.L.C.      | 373671                         |
| 508 W Wall Street, Suite 1000 | Action Number:                 |
| Midland, TX 79701             | 344283                         |
|                               | Action Type:                   |
|                               | [C-103] Sub. Workover (C-103R) |

## CONDITIONS

| Created<br>By |      | Condition<br>Date |
|---------------|------|-------------------|
| kfortner      | None | 5/24/2024         |