<u>District I</u> 1623 N French Dr., Hobbs, NM 88240 Phone (\$75) 393-6161 Fax. (\$75) 393-0720

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT Operator Name API Number 30-025-02952 MORNINGSTAR OPERATING, LLC Property Name CENTRAL VACUUM UNIT 3 1. Surface Location UL - Los Section Township Range Feet from N/S Line Feet From County FNL 30 17S 35E 330 1650 **LEA** Well Status TA'D WELL SHUT-IN INJECTOR PRODUCER DATE YES (NO) YES NO SWD OIL 9-3-24 INI **OBSERVED DATA** (A)Surface (B)Interm(1) (C)Interm(2) (E)Tubing (D)Prod Csng Pressure 0 250 100 Flow Characteristics Puff CO2 Y / (N) YIN YIN Y/N WTR Steady Flow YIN YIN GAS Surges YID YIN YIN Type of Field Down to nothing Q/N Y/N YIN YIN Interred for Waterikood if Gas or Oil Y / (N) YIN Y/N YIN Water YIN Y/N YIN Y/N Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. Signature OIL CONSERVATION DIVISION Printed name. Entered into RBDMS Title Re-test actilisers ca E-mail Address: Date. Phone Wintess

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 391773

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	391773
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	11/18/2024