

D000000K

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Dwight A. Tipton	API Number 30-005-60875
Property Name Plains 29	Well No. #001

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
D	29	10S	28E	660	N	660	W	Eddy

Well Status

TA'D WELL	SHUT-IN	INJ	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☒ NO ☐	INJ ☐	SWD ☒	OIL ☐ GAS ☐	10/11/2024

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	☒			☒	☒
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	☒ Y / N	CO2
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BWT - OK

Signature: <i>Justin Alexander</i>		OIL CONSERVATION DIVISION	
Printed Name: Justin Alexander		Entered into RBDMS	
Title:		Re-test	
E-mail Address: azcobio@hotmail.com			
Date: 10/10/24	Phone: 575-631-4282		
Witness: <i>Raymond Allen</i>			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 392859

CONDITIONS

Operator: DWIGHT A TIPTON 2009 South Main Street Lovington, NM 88260	OGRID: 6550
	Action Number: 392859
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	11/19/2024