

Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens & Johnson Operating Co.	API Number 30-015-02211
Property Name State 'BN'	Well No 2

Surface Location

U.L. - Lot 0	Section 11	Township 19S	Range 28E	Feet from 660	N/S Line FSL	Feet From 1980	E/W Line FEL	County Eddy
------------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	-----------------------

Well Status

TA'D Well YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE 7/18/2024
--	--	--	---	--------------------------

OBSERVED DATA



	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	860
Flow Characteristics					
Puff	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	CO2 <input type="checkbox"/>
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	<input checked="" type="radio"/> Y/ <input type="radio"/> N	If applicable type
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	fluid injected for
Water	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OIK

Signature: 	OIL CONSERVATION DIVISION
Printed name Mark Hope	Entered RBDMS
Title: Pumper	Re-test
E-mail Address hope-mark53@yahoo.com	
Date: 7/18/2024	Phone: 575-748-5629
Witness: 	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 367080

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 367080
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024