

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens + Johnson Operating Co.	API Number 30-015-02252
Property Name East Millman Unit	Well No 153

Surface Location									
U.L. - Lot C	Section 14	Township 19S	Range 28E		Feet from 660	N/S Line FWL	Feet From 1980	E/W Line FWL	County Eddy

Well Status						DATE
TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ	SWD	PRODUCER OIL ☐ GAS ☐		7/18/2024

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	900
Flow Characteristics					
Puff	Y/ ☒	Y/ ☒	Y/ ☒	Y/ ☒	CO2 ☐
Steady Flow	Y/ ☒	Y/ ☒	Y/ ☒	Y/ ☒	WTR ☒
Surges	Y/ ☒	Y/ ☒	Y/ ☒	Y/ ☒	GAS ☐
Down to nothing	☒ N	☒ N	Y/ ☒	☒ N	If applicable type
Gas or Oil	Y/ ☒	Y/ ☒	Y/ ☒	Y/ ☒	fluid injected for
Water	Y/ ☒	Y/ ☒	Y/ ☒	Y/ ☒	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT.OK

Signature: Mark Hope	OIL CONSERVATION DIVISION
Printed name Mark Hope	Entered RBDMS
Title: Pumper	Re-test
E-mail Address hope-mark53@yahoo.com	
Date: 7/18/2024	Phone 575-748-5629
Witness Barbara yank	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oecd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 367059

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 367059
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024