

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name: LH Operating, LLC
 Property Name: Skelly Unit
 API Number: 30015-05343
 Well No.: 41

Surface Location
 UL Lot: A Section: 22 Township: 17S Range: 31E
 Feet from: 330 N/S Line: N Feet From: 330 E/W Line: E County: Eddy

Well Status
 YES TA'D WELL NO SHUT-IN YES INJECTOR NO SWD OIL PRODUCER GAS DATE: 7/8/2024

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	6			6	1050
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
 BHT-OK- Well is shut in. Replacing main inj. line

Signature: Michael Burton
 Printed name: Mike Burton
 Title:
 E-mail Address: Mike@lhoperating.com
 Date:
 Phone: 575-499-5306
 Witness: [Signature]
 OIL CONSERVATION DIVISION
 Entered into RBDMS
 Re-test

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 366717

CONDITIONS

Operator: LH Operating, LLC 3730 Kirby Drive Houston, TX 77098	OGRID: 329319
	Action Number: 366717
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024