

District I

625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name TEAM OPERATING	* API Number 30-025-10577
Property Name LANGLIE MATTIX PENROSE SAND UNIT	Well No. 361

7. Surface Location

UL - Lot B	Section 34	Township 22S	Range 37E	Feet from 660	N/S Line N	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	<input checked="" type="radio"/> NO	<input checked="" type="radio"/> YES	SHUT-IN NO	<input checked="" type="radio"/> INJ	INJECTOR SWD	OIL PRODUCER	GAS	DATE 08/27/2024
------------------	-------------------------------------	--------------------------------------	---------------	--------------------------------------	-----------------	-----------------	-----	---------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	17	17		15	17
Flow Characteristics					
Puff	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	<input checked="" type="radio"/> Y / N	CO2 <input type="checkbox"/>
Steady Flow	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y / N	<input checked="" type="radio"/> Y / N	Y / N	<input checked="" type="radio"/> Y / N	Type of Fluid
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	Injected for
Water	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	<input checked="" type="radio"/> Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

PRODUCTION CASING HAD A SMALL AMOUNT OF WATER.

Signature: Austin L Musgrave	OIL CONSERVATION DIVISION
Printed name: AUSTIN L. MUSGRAVE	Entered into RBDMS
Title: FIELD SUPERVISOR	Re-test [Signature]
E-mail Address: AUSTIN.MUSGRAVE@TEAMOPERATING.COM	
Date: 08/27/2024	Phone: (432) 701-5144
Witness:	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 411428

CONDITIONS

Operator: TEAM OPERATING, L.L.C. PO Box 835 Pinehurst, TX 77362	OGRID: 332148
	Action Number: 411428
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/16/2024