

DECEMBER  
District 2 Artesia

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name <b>SOUTHWEST ROYALTIES</b>	API Number <b>30-025-06893</b>
Property Name <b>CENTRAL DRINKARD UNIT</b>	Well No. <b>160</b>

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
<b>E</b>	<b>29</b>	<b>21S</b>	<b>37E</b>	<b>1980</b>	<b>N</b>	<b>660</b>	<b>W</b>	<b>Lea</b>

Well Status


TA'D WELL YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	SHUT-IN YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	INJECTOR <input checked="" type="checkbox"/> INJ	SWD	PRODUCER OIL <input type="checkbox"/> GAS <input type="checkbox"/>	DATE <b>8/1/24</b>
--	--	---	-----	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csgng	(E)Tubing
Pressure	<b>0</b>	<b>200</b>		<b>0</b>	<b>400</b>
<u>Flow Characteristics</u>					
Puff	Y / <input checked="" type="checkbox"/> N	<input checked="" type="checkbox"/> Y / N	Y / N	Y / <input checked="" type="checkbox"/> N	CO2 _____ WTR <input checked="" type="checkbox"/>
Steady Flow	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / <input checked="" type="checkbox"/> N	GAS _____
Surges	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / <input checked="" type="checkbox"/> N	Type of Fluid
Down to nothing	<input checked="" type="checkbox"/> Y / N	<input checked="" type="checkbox"/> Y / N	Y / N	<input checked="" type="checkbox"/> Y / N	Injected for
Gas or Oil	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / <input checked="" type="checkbox"/> N	Waterflood if
Water	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / <input checked="" type="checkbox"/> N	applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Intermidate blew down 5 sec monitor gauge did not gain pressure

Signature: 	OIL CONSERVATION DIVISION
Printed name: <b>RYAN MARTIN</b>	Entered into RBDMS
Title: <b>AGENT</b>	Re-test
E-mail Address: <b>MYMERCH@PENROCOIL.COM</b>	
Date:	Phone: <b>575-492-1236</b>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 377396

**CONDITIONS**

Operator: SOUTHWEST ROYALTIES INC P O BOX 53570 Midland, TX 79710	OGRID: 21355
	Action Number: 377396
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
kfortner	None	12/17/2024