



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4/3/25 Operator San Juan Resources API # 30-039-23288

Property Name CLARK #010 Location: Unit D Section 5 Township 24N Range 03W
(Well Name and Number)

Pressure (Shut-in or Producing) Shut-in Tubing 47 Intermediate N/A Casing 61 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time,	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	61	N/A	N/A	N/A		N/A
10 minutes	0	61	↓	↓	↓		↓
15 minutes	0	61	↓	↓	↓		↓
20 minutes			↓	↓	↓		↓
25 minutes			↓	↓	↓		↓
30 minutes			↓	↓	↓		↓
5 minute SI	0	61					

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS: No gas or water on Bradenhead

By Wyatt Templeton
Lease Operator
(Position)

Witness _____

NMOCD Test Area:

1

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455021

CONDITIONS

Operator: SAN JUAN RESOURCES, INC. 1499 Blake St, #10C Denver, CO 80202	OGRID: 20208
	Action Number: 455021
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	5/7/2025