

State Of New Mexico
Energy, Minerals and Natural Resources Department

07-Jul-25

PETRO MEX LLC
P.O. Box 6724
Farmington, NM 87499

Pre Enforcement Notification

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-045-24633] TRS-EVI #001

OGRID: 236452

H-11-29N-15W 2130 FNL 810 FEL

Inspection Date	Type Inspection	Inspector	Inspection No.
7/7/2025	Complainant Response	[TV] Thomas Vermersch	iTV2518857300
Violation	Title		Corrective Action Due
cTV2518866683	19.15.10.8 Safety Procedures for Drilling and Production	General Housekeeping Required	10/5/2025
	<i>(There is some heavy weed growth around the production tanks that need removal. Unable to preform a proper inspection due to the weeds. There are also some weeds around the wellhead and near other equipment that needs removed. Please have all weeds removed from around tanks and equipment.)</i>		
cTV2518866684	19.15.16.8 Sign on Wells	Inaccurate Information	10/5/2025
	<i>(Well sign missing the required footage and unit letter or quarter/quarter section.)</i>		
cTV2518866685	19.15.29 Releases Surface Leaks/Spills		10/5/2025
	<i>(There is some staining around the separator. There is some staining around the wellhead and under the pumpjack motor. There appears to be some staining near the production tanks but is hard to see with the excessive weeds growth. Please have all staining cleaned up per NMAC 19.15.29.8A.)</i>		

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.