District 2 Artesia

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RRA	DENHE	AD TEST	REPORT
TO TAKE	THE RESTRICT		REAL PROPERTY OF THE PROPERTY

SAGUARO PETROLEUM 30-01						
PUCKETT A Property Name				Well No.		
⁷ Surface Location						
UL-Lot Section Township Range 31E	Feet from 2615	N/S Line Feet From 2540		County DDY		
Well Status						
YES TA'D WELL NO YES SHUT-IN	NO INJ INJECTOR SWI	OIL PRODUCER	GAS $8/5/2$	E S		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			0	25
Flow Characteristics			/		
Puff	(Y) N	Y / N /	Y //N	(Y) N	CO2
Steady Flow	Y/N	YIN	y / N	Y / (N)	WTR _
Surges	Y /(N)	Y/N	/Y / N	Y / (N)	Type of Fluid
Down to nothing	(Y)/ N	Y/N	Y/N	(Y)/ N	Injected for
Gas or Oil	Y/N	/ Y / N	Y / N	Y /(N)	Waterfluod if applies.
Water	Y /(N)	Y / N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.	
PUFF, GOOD TEST, NO PRESSURE	

OIL CONSERVATION DIVISION
Entered into RBDMS
Re-test

Released to Imaging: 8/20/2025 10:47:38 AM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 495088

CONDITIONS

Operator:	OGRID:
Saguaro Petroleum, LLC	373933
15 Smith Rd	Action Number:
Midland, TX 79705	495088
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	8/13/2025