## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRA	DENHEAD TEST REPORT	[			
Operator Name			API Number		
K P KAUFFMAN COMPANY, INC. Property Name			30-015-05685		
EAST SHUGART UNIT			Well No. # 029		
	<sup>7</sup> Surface Location				
UL-Lot Section Township Range  N 34 185 316	Feet from N/S Line 330 S	Feet From 2310	E/W Line	E D D Y	
	Well Status				
YES TA'D WELL NO YES SHUT-IN NO	INJ SWD OIL	PRODUCER	s 3/1	DATE 9 12025	

# **OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	/	/	0	0
Flow Characteristics					
Puff	Y / 🔊	Y/N	Y/N	Y/ED	CO2
Steady Flow	Y / 10	YIX	YIN	Y/D	GAS
Surges	YIN	Y/ N	y/I, N	Y / 🔊	Type of Fluid
Down to nothing	ON	Y/N	Y/N	Ø N	Injected for Waterflood if
Gas or Oil	YIO	Y/N	Y/N	Y / 🔊	applies
Water	Y/(8)	Y/N	Y/N	YIO	

PWO BHT-OK	rarding bleed down or continuous build up if applies.  PACKER - 3208
2024 DATE 10/10/2026	

Signature.		OIL CONSERVATION DIVISIO		
Printed name:		Entered into RBDMS		
Title		Re-test		
E-mail Address:				
Date:	Phone:			
	Witness Wan pld Doll			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 445422

## **CONDITIONS**

Operator:	OGRID:	
K P KAUFFMAN COMPANY INC	228296	
1700 Lincoln Street	Action Number:	
Denver, CO 80203	445422	
	Action Type:	
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)	

## CONDITIONS

Created By		Condition Date
ronald.he	Pr None	8/20/2025