District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 Revised April 3, 2017

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

<u>Pit, Below-Grade Tank, or</u> Proposed Alternative Method Permit or Closure Plan Application

Proposed Alternative Method Permit or Closure Plan Application
Type of action: Below grade tank registration Permit of a pit or proposed alternative method Closure of a pit, below-grade tank, or proposed alternative method Modification to an existing permit/or registration Closure plan only submitted for an existing permitted or non-permitted pit, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
1. Operator:Harvest Midstream
Address: _1111 Travis Street, Houston, TX 77002
Facility or well name: <u>LINDA NYE #1A</u>
API Number: <u>30-045-22277</u> OCD Permit Number: <u>Facility ID:</u>
U/L or Qtr/QtrD Section20 Township30N Range8W
Center of Proposed Design: Latitude36.800960Longitude107.703676NAD83
Surface Owner: Federal State Tribal Trust or Indian Allotment
Pit: Subsection F, G or J of 19.15.17.11 NMAC Temporary: Drilling Workover Drilling Workover Permanent Emergency Cavitation P&A Multi-Well Fluid Management Low Chloride Drilling Fluid yes no Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other String-Reinforced Liner Seams: Welded Factory Other Volume: bbl Dimensions: L x W x D Liner Seams: Welded Factory Other Liner Seams: Description Liner Seams Liner
3.
Below-grade tank: Subsection I of 19.15.17.11 NMAC
Volume:45bbl Type of fluid: Produced Water or other produced liquids (RCRA exempt)
Tank Construction material:Steel tank with expanded metal top
☐ Secondary containment with leak detection ☐ Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other
Liner type: Thicknessmil
4. Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.
5.
Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church)
Four foot height, four strands of barbed wire evenly spaced between one and four feet
Alternate. Please specify:

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)				
☐ Screen ☐ Netting ☐ Other Expanded Metal				
☐ Monthly inspections (If netting or screening is not physically feasible)				
7.				
Signs: Subsection C of 19.15.17.11 NMAC				
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers				
☐ Signed in compliance with 19.15.16.8 NMAC				
8.				
Variances and Exceptions:				
Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.				
Please check a box if one or more of the following is requested, if not leave blank: Variance(s): Requests must be submitted to the appropriate division district for consideration of approval.				
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.				
9. Siting Criteria (regarding permitting): 19.15.17.10 NMAC				
Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept	otable source			
material are provided below. Siting criteria does not apply to drying pads or above-grade tanks.				
Conoral siting				
General siting				
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank.	Yes No			
- MM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	NA _			
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit.	⊠ Yes □ No □ NA			
NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	1771			
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes ⊠ No			
adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality				
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ⊠ No			
Within an unstable area. (Does not apply to below grade tanks)	□ Vas □ Na			
 Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ⊠ No			
Within a 100-year floodplain. (Does not apply to below grade tanks)	☐ Yes ⊠ No			
- FEMA map				
Below Grade Tanks				
W/4: 100 C 4 C 4: 1 C : 4				
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark).	☐ Yes ⊠ No			
- Topographic map; Visual inspection (certification) of the proposed site				
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;.	☐ Yes ⊠ No			
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site				
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)				
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole,				
or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.)	☐ Yes ☐ No			
- Topographic map; Visual inspection (certification) of the proposed site				
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial	☐ Yes ☐ No			
 application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image 	_			
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application.	☐ Yes ☐ No			
NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site				

Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit Non-low chloride drilling fluid	
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).	
- Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.	
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 N Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19. and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	NMAC 15.17.9 NMAC
11. Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC	
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the attached.	documents are
 ☐ Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC ☐ Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC 	
☐ Climatological Factors Assessment ☐ Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC	
 □ Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC □ Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC □ Quality Control/Quality Assurance Construction and Installation Plan 	
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan	
Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan	
Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	
13. Proposed Closure: 19.15.17.13 NMAC	
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well F	luid Management Pit
☐ Alternative Proposed Closure Method: ☐ Waste Excavation and Removal ☐ Waste Removal (Closed-loop systems only)	-
On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method	
14.	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)	
 ☐ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC ☐ Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC ☐ Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC 	
Nr.	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. In 19.15.17.10 NMAC for guidance.	
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engin	☐ Yes ☐ No ☐ NA
- eer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application.	□ Ves □ No
- NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	Yes No
Written confirmation or verification from the municipality; Written approval obtained from the municipality Within 300 feet of a wetland.	☐ Yes ☐ No
US Fish and Wildlife Wetland Identification map: Topographic map: Visual inspection (certification) of the proposed site	

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ No			
Within the area overlying a subsurface mine.				
withten commination of verification of map from the TVW EVITATE Firming and Withten Division	□ No			
W'.1.'				
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map Yes	□ No			
Within a 100-year floodplain.				
- FEMA map				
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved) Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC				
17. Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.				
Name (Print): Monica Smith Title: Environmental Specialist				
Signature: Date:				
Signature				
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625				
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625				
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625				
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625				
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625	re report.			
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625	re report.			

22.	
Operator Closure Certification:	
I hereby certify that the information and attachments submitted with this closure report is belief. I also certify that the closure complies with all applicable closure requirements and	
Name (Print): Monica Smith	Title: _Environmental Specialist
Signature: Monica Smith	Date: 9/5/2025
e-mail address:monica.smith@harvestmidstream.com Telephone:	505-632-4625



July 31, 2025

New Mexico Oil Conservation Division

New Mexico Energy, Minerals, and Natural Resources Department 1220 South St. Francis Drive Santa Fe. New Mexico 87505

Re: BGT Closure

Linda Nye #1A BGT API Number: 30-045-22277 Harvest Four Corners, LLC

To Whom It May Concern:

Ensolum, LLC (Ensolum) on behalf of Harvest Four Corners, LLC (Harvest), is submitting this letter requesting closure for the below grade tank (BGT) at the Linda Nye 1A BGT (API: 30-045-22277) located in Unit D, Section 20,Township 30 North, Range 8 West, in San Juan County, New Mexico. Harvest followed the closure plan for the BGT approved by the New Mexico Oil Conservation Commision (NMOCD) on April 14, 2025. The approved closure plan is included in Appendix A.

Harvest sent an email on June 25, 2025, to the NMOCD and the surface owner, the Bureau of Land Management (BLM), providing a 72-hour notification for BGT removal and closure sampling (Appendix B). Harvest removed the BGT according to the approved closure plan. On June 30, 2025, Harvest collected one five-point composite soil sample from the floor of the excavation and submitted it to Eurofins Environmental Analysis Laboratory in Albuquerque, New Mexico. No wet or stained soil or odor was observed, and the sampling was conducted with an NMOCD representative on location. A diagram showing the composite soil sample location is included in Appendix C. A photograph of the BGT footprint following removal is included in Appendix D.

The soil sample was analyzed for benzene, toluene, ethylbenzene, total xylene (BTEX) by Environmental Protection Agency (EPA) Method 8021B, Diesel Range Organics (DRO), motor oil range organics (MRO), and gasoline range organics (GRO) by EPA Method 8015M, and chloride by EPA Method 300.0. The analytical results for the soil sample indicate no analytes were detected above laboratory reporting limits and therefore meet the Table 1 Closure Criteria for Soils Beneath Below-Grade Tanks, Drying Pads Associated with Closed-Loop Systems and Pits where Contents are Removed (19.15.17.13 of the New Mexico Administrative Code). Soil sample analytical results are presented in the attached Table 1 and the laboratory analytical report is included in Appendix E.

Harvest has backfilled the former BGT area to match the grade of the existing pad. Photographic documentation is included in Appendix D. When the facility is no longer being used, the area will be reclaimed according to the closure plan.

Linda Nye 1A BGT

Ensolum appreciates the opportunity to submit this report to the NMOCD on behalf of Harvest. If there are any questions or comments regarding this report, please contact the undersigned.

Sincerely,

Ensolum, LLC

Eric Carroll Project Geologist

(303) 842-9578 ecarroll@ensolum.com

Exiz Conoll

cc: Monica Smith, Harvest Four Corners, LLC

Attachments:

Table 1 Soil Sample Analytical Results

Appendix A NMOCD Approved Closure Plan
Appendix B Notification of Closure Sampling
Appendix C Soil Sample Collection Field Forms

Appendix D Photographic Log

Appendix E Laboratory Analytical Report



TABLE 1



TABLE 1

SOIL SAMPLE ANALYTICAL RESULTS LINDA NYE 1A BGT

Harvest Four Corners, LLC San Juan County, New Mexico

Sample I.D.	Sample Date	Sample Depth (feet bgs)	Benzene (mg/kg)	Toluene (mg/kg)	Ethylbenzene (mg/kg)	Xylenes (mg/kg)	Total BTEX (mg/kg)	TPH GRO (mg/kg)	TPH DRO (mg/kg)	TPH MRO (mg/kg)	Total TPH (GRO+DRO+MRO) (mg/kg)	Chloride (mg/kg)
		for Soils Beneath water <50 feet)	10	NE	NE	NE	50	NE	NE	NE	100	600
BGT Bottom	6/30/2025	4	<0.024	<0.048	<0.048	<0.097	<0.097	<4.8	<9.6	<48	<48	<60

Notes

bgs: below ground surface

mg/kg: milligrams per kilogram

NE: Not Established

NMOCD: New Mexico Oil Conservation Division

BTEX: Benzene, Toluene, Ethylbenzene, and Xylenes

GRO: Gasoline Range Organics

DRO: Diesel Range Organics

MRO: Motor Oil/Lube Oil Range Organics

TPH: Total Petroleum Hydrocarbon

< 0.037: indicates result less than the stated laboratory reporting limit (RL)



APPENDIX A NMOCD Approved Closure Plan

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-144 Revised April 3, 2017

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

<u>Pit, Below-Grade Tank, or</u> Proposed Alternative Method Permit or Closure Plan Application

1 toposed Thermany of Wiethout 1 ethnic of Closure I fair Tippinearion
Type of action: Below grade tank registration BGT1 Permit of a pit or proposed alternative method Closure of a pit, below-grade tank, or proposed alternative method Modification to an existing permit/or registration Closure plan only submitted for an existing permitted or non-permitted pit, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
1. Operator:Harvest Midstream
Address: _1111 Travis Street, Houston, TX 77002
Facility or well name: LINDA NYE #1A
API Number: _3004522277 OCD Permit Number: _Facility ID:
U/L or Qtr/Qtr D Section 20 Township 30N Range 8W
Center of Proposed Design: Latitude Longitude NAD83
Surface Owner: Federal State Private Tribal Trust or Indian Allotment
☐ Pit: Subsection F, G or J of 19.15.17.11 NMAC Temporary: ☐ Drilling ☐ Workover ☐ Permanent ☐ Emergency ☐ Cavitation ☐ P&A ☐ Multi-Well Fluid Management Low Chloride Drilling Fluid ☐ yes ☐ no ☐ Lined ☐ Unlined Liner type: Thickness mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other ☐ String-Reinforced Liner Seams: ☐ Welded ☐ Factory ☐ Other Volume: bbl Dimensions: L x W x D
3. Below-grade tank: Subsection I of 19.15.17.11 NMAC
Volume: 45 bbl Type of fluid: Produced Water or other produced liquids (RCRA exempt)
Tank Construction material:Steel tank with expanded metal top
Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other
Liner type: Thicknessmil
4.
☐ <u>Alternative Method</u> :
Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.
5. Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) ☐ Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church) ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet ☐ Alternate. Please specify: Hog wire fence with T-posts and top rail

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
☐ Screen ☐ Netting ☒ Other Expanded Metal	
☐ Monthly inspections (If netting or screening is not physically feasible)	
7.	
Signs: Subsection C of 19.15.17.11 NMAC	
☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
☐ Signed in compliance with 19.15.16.8 NMAC	
Variances and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	otable source
General siting	
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank. - ☑ NM Office of the State Engineer - iWATERS database search; ☐ USGS; ☐ Data obtained from nearby wells	⊠ Yes □ No □ NA
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ⊠ No
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ⊠ No
 Within an unstable area. (Does not apply to below grade tanks) Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ⊠ No
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	☐ Yes ⊠ No
Below Grade Tanks	
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark).	☐ Yes ⊠ No
- Topographic map; Visual inspection (certification) of the proposed site	
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial application.	☐ Yes ☐ No
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No

Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit Non-low chloride drilling fluid	
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).	
- Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.	☐ Yes ☐ No
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	103 110
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 Naturations: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the do attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19. and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	NMAC 15.17.9 NMAC
11.	
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the do attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC	_
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the	documents are
 attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC 	
Climatological Factors Assessment	
☐ Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC	
Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC	
Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC	
Quality Control/Quality Assurance Construction and Installation Plan	
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC	
Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC	
 Nuisance or Hazardous Odors, including H₂S, Prevention Plan Emergency Response Plan 	
Oil Field Waste Stream Characterization	
Monitoring and Inspection Plan	
Erosion Control Plan	
Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	
13.	
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.	
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well F	luid Management Pit
Alternative	
Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only)	
On-site Closure Method (Only for temporary pits and closed-loop systems)	
☐ In-place Burial ☐ On-site Trench Burial	
Alternative Closure Method	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be closure plan. Please indicate, by a check mark in the box, that the documents are attached. □ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
15.	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. In 19.15.17.10 NMAC for guidance.	
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engin	☐ Yes ☐ No ☐ NA
-	Yes No
- eer - iWATERS database search; USGS; Data obtained from nearby wells	
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification man: Tonographic man: Visual inspection (certification) of the proposed site	☐ Yes ☐ No

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No☐ Yes ☐ No			
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	i ies i ino			
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No			
Within a 100-year floodplain FEMA map	Yes No			
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved) Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC				
17. Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and believed.	ef.			
Name (Print): Monica Smith Title: Environmental Specialist				
Signature:				
e-mail address:monica.smith@harvestmidstream.com Telephone:505-632-4625	-			
18. OCD Approval: ☐ Permit Application (including closure plan) ☐ Closure Plan (only) ☐ OCD Conditions (see attachment)				
OCD Representative Signature: Joel Stone Approval Date: 04/14/2	2025			
Title: Environmental Scientist & Specialist-A OCD Permit Number: BGT1				
19. Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date:				
Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not section of the form until an approved closure plan has been obtained and the closure activities have been completed.				
Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not section of the form until an approved closure plan has been obtained and the closure activities have been completed.	complete this			

22. Operator Closure Certification:	
	ents submitted with this closure report is true, accurate and complete to the best of my knowledge and th all applicable closure requirements and conditions specified in the approved closure plan.
Name (Print):	Title:
Signature:	Date:
e-mail address: Tele	phone:

Harvest Four Corners, LLC San Juan Basin Below Grade Tank Closure Plan

Facility Name: Linda Nye #1

API No.: 3004509369

Description: Unit D, Section 20, Township 30N, Range 8W, San Juan County, New Mexico

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure requirements for this below grade tank (BGT) for Harvest Four Corners, LLC (Harvest).

General Plan

- 1. Harvest will obtain approval of this closure plan prior to commencing closure of the BGT at this location pursuant to 19.15.17.13.C (1) NMAC.
- 2. Harvest will notify surface owners by certified mail, return receipt requested, that the operator plans closure operations at least 72 hours, but no more than 1 week, prior to any closure operations. Notice will include:
 - a) Well Name
 - b) API
 - c) Well Location
 - *Harvest will notify government agencies by email of closure activities.
- 3. The NMOCD will be notified by email that the operator plans closure operations at least 72 hours, but no more than one week, prior to any closure operations.


Notice will include:

- a) Well Name
- b) API
- c) Well Location
- 4. Within 60 days of cessation of operations, all liquids and sludge will be removed from the BGT prior to implementing closure activities and will dispose of the liquids and sludge at an approved facility.
 - a) Soil, tank bottoms, and exempt wastes impacted by petroleum hydrocarbons will be disposed of at: *Envirotech: Permit #NM01-0011*
 - b) Produced water will be disposed of at: *Basin Disposal: Permit #NM01-005* or *Agua Moss: Permit #NM-009*
- 5. Within six months of cessation of operations, the BGT will be removed and disposed of at an appropriate division approved facility, or recycled, reused, or reclaimed in a manner that is approved by the district office. Equipment associated with the BGT will be removed unless the equipment will continue to be used for on-site operation.
- 6. Harvest will collect a closure sample of the soil beneath the location of the BGT or liner that is being closed. The closure sample will consist of a 5-point composite sample to include any obvious stained or wet soils, or other evidence of contamination. The closure sample will be analyzed for all constituents listed in Table I below, including chloride, total petroleum hydrocarbons (TPH, C-6-C36), benzene, toluene, ethylbenzene, and total xylenes (BTEX).

	,	Table I				
Closure Cr		w-Grade Tanks, Drying Pads Associa	ated with			
Closed-Loop Systems and Pits where Contents are Removed						
Depth below bottom of pit	Constituent	Limit**				
to groundwater less than						
10,000 mg/l TDS						
	Chloride	EPA 300.0	600 mg/kg			
	TPH	EPA SW-846	100 mg/kg			
≤50 feet		Method 418.1				
	BTEX	EPA SW-846 Method 8021B	50 mg/kg			
		or 8260B				
	Benzene	EPA SW-846 Method 8021B	10 mg/kg			
		or 8015M				
	Chloride	EPA 300.0	10,000 mg/kg			
	TPH	EPA SW-846	2,500 mg/kg			
51 feet-100 feet		Method 418.1				
	GRO+DRO	EPA SW-846	1,000 mg/kg			
		Method 8015M				
	BTEX	EPA SW-846 Method 8021B	50 mg/kg			
		or 8260B				
	Benzene	EPA SW-846 Method 8021B	10 mg/kg			
		or 8015M				
	Chloride	EPA 300.0	20,000 mg/kg			
	TPH	EPA SW-846	2,500 mg/kg			
> 100 feet		Method 418.1				
	GRO+DRO	EPA SW-846	1,000 mg/kg			
		Method 8015M				
	BTEX	EPA SW-846 Method 8021B	50 mg/kg			
		or 8260B				
	Benzene	EPA SW-846 Method 8021B	10 mg/kg			
		or 8015M				

- 7. Harvest will close this BGT based on the requirements for groundwater less than 50 feet. It is estimated that groundwater is less than 50 feet based on New Mexico Office of State Engineer permitted water well, SJ 01742, 1,000 feet to the south, which has a recorded depth to water of 11 feet below ground surface; see *Figure ,1 Site Location Map.* The BGT is also located 300 feet west of a permanent residence.
- 8. If any contaminant concentration is higher than the parameters listed in Table I, additional delineation may be required based on the review of the results. Harvest will receive division approval before proceeding with additional closure activities. If all contaminant concentrations are less than, or equal to, the parameters in Table I above, the operator can proceed to backfill with non-waste containing, uncontaminated earthen material.
- 9. After closure has occurred, the former BGT area will be reclaimed if it is no longer being utilized for the continued operation of the facility. The area will be reclaimed by substantially restoring the surface area to the condition that existed prior to oil and gas operations. The soil cover will be constructed to the sites existing grade and prevent ponding of water and erosion of the cover materials. The soil shall consist of the background thickness of topsoil, or one foot of suitable material to establish vegetation on the site, whichever is greater. The area will be reclaimed as early as practicable, and as close to their original condition as possible. They shall be maintained in such a way as to control dust and minimize erosion.

- 10. Reclamation will be completed in accordance with the requirements listed in NMAC 19.15.17.13.H(5).
 - a) The former BGT area will be reclaimed as early and as nearly practicable to their original condition, or their final land use, and shall be maintained to control dust and minimize erosion to the extent practicable.
 - b) Topsoil and subsoil will be replaced to their original relative positions and contoured as to achieve erosion control, long term stability and preservation or water flow patterns. The reclaimed area will be reseeded in the first favorable growing season following closure of the BGT.
 - c) Reclamation will be considered completed when all ground disturbance activities of the site have been completed, and a uniform vegetative cover has been established that reflects plus or minus 50% of the pre-disturbance levels, and a total perfect overage of at least 70% of pre-disturbance levels, excluding noxious weeds.
 - d) Re-vegetation and reclamation obligations imposed by other federal or tribal agencies managed by those agencies shall supersede these provisions and govern the obligations of any operator subject to these provisions, provided that the other requirements provide equal or better protection of fresh water, human health, and the environment.
 - e) The operator shall notify the division when reclamation and re-vegetation are complete.
- 11. Within 60 days of closure of the BGT, Harvest will submit a closure report to the Aztec office of the NMOCD. Closure report will be filed on form C-144 and include the following:
 - a) Proof of closure notice to division and surface owner.
 - b) Confirmation sampling analytical results.
 - c) Photo documentation of the site reclamation.
 - d) Table I groundwater criteria request, groundwater information and required approval (if needed).





Site Location Map

Linda NYE 1A Harvest Four Corners, LLC 36.800960, -107.703668 San Juan County, New Mexico **FIGURE**

1

Released to Imaging: 9/18/2025 1:33:44 PM

STATE ENGINEER OFFICE

WELL RECORD

Section 1. GENERAL INFORMATION

(A) Owner of Street or City and	f well A4 Post Office Ac State BL	4800 M. 601310 BUFIEL	SIER	R A	x 87	Owner's V	Well No. 50-/	1742
			,		and is located		,	
						30 My / Bange	8 W	_N.M.P.M.
					ې .		$7 \ln z$	
c Lot N	36	of Block No	6	of th	SAN TUAL	AMBINENCES	TATES F	 *3
Subdi	vision, recorde	d in SAN	JUA	U .	County.	E. N.M. 87	FFICE	
d. X=	· · · · · ·	feet, Y=		feet, N	I.M. Coordinate	System		Zone in Grant.
						www.icense No. U		
Address///3	BU,5	VELLVA	w, fr	ARMIN	GTONIL	EWHEX	1008	/40/
Drilling Began	5-11-8	4 Comp	leted 3-	12-89	Type tools	ADLE TOOL	Size of hole	フ ''in.
Elevation of la	nd surface or _			at w	ell is <u>/ Z '</u>	ft. Total depth of	well	ft.
Completed wel	l is	hallow 🗆 a	rtesian.		Depth to water	r upon completion of	well	ft.
-		Sect	tion 2. PRIN	CIPAL WATE	ER-BEARING ST			
	in Feet	Thickness in Feet		Description of	Water-Bearing I	Formation	Estimated Yi (gallons per mi	
From	To /	170	17.	4.5	25 + G	7		_
			150	DLDER	rs t C	TAVEL	18 GAL	77
Dismotor	Pounds	Throada		n 3. RECORI in Feet	OF CASING		Perfora	tions
Diameter (inches)	per foot	Threads per in.	Тор	Bottom	Length (feet)	Type of Shoe	From	To
2"	23#	NA	18	SURFAC 17	18'	NA	13'	12'
		//				/		
		Section	on 4. RECO	RD OF MUDI	DING AND CEM	(ENTING		
Depth From	in Feet To	Hole Diameter	Saci of M		Cubic Feet of Cement	Method	of Placement	
110111								
1	12	9						
7	10							
	<u> </u>	<u></u>						
					NG RECORD			
Address					No.	Depth in Fee	et Cub	ic Feet
						Top B	ottom of C	Cement
Plugging appro	-				2			
		State Eng	ineer Repres	entative	3 4			
1	FOR USE OF STATE ENGINEER ONLY							
Date Received	May 15,	1984		Qua	d	FWL	FSL_	
File No	SJ-1742				1	Location No. 30N.		
File No	ng: 9/18/2025	1:33:44 PM				san juan count		

Depth i	n Feet	Thioknoon	Section 6. LOG OF HOLE		
From	To To	Thickness in Feet	Color and Type of Material Encountered		
-0	8'	8'	SAND & SHALE		
8	17'	9'	BOULDER'S + GAVEL		
	(,		
		Light to the control of the control			
AND		LE CONTROLLE LANCE TO BE OF STREET			
			•.		

Section 7. REMARKS AND ADDITIONAL INFORMATION

The undersigned hereby certifies that, to the best of his knowledge and belief, the foregoing is a true and correct record of the above described hole.

INSTRUCTIONS: This form should be executed in triplicate, preferably typewritten, and submitted to the appropriate district office of the State Engineer. All sections, exce Section 5, shall be answered as completely accurately as possible when any well is drilled, repaired or deepened. When this form is used as a plugging record, only Section 1(a) and Section 5 need be completed.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 451236

CONDITIONS

Operator:	OGRID:
Harvest Four Corners, LLC	373888
1755 Arroyo Dr	Action Number:
Bloomfield, NM 87413	451236
	Action Type:
	[C-144] Below Grade Tank Plan (C-144B)

CONDITIONS

Created By		Condition Date
joel.stone	None	4/14/2025



APPENDIX B

Notification of Closure Sampling

From: Chad Snell - (C)

To: Hall, Brittany, EMNRD

Cc: Enviro, OCD, EMNRD; Stone, Joel, EMNRD; Adeloye, Abiodun A; jcraun@blm.gov; Monica Smith; Brooke Herb;

Bratcher, Michael, EMNRD; Barr, Leigh, EMNRD; Wells, Shelly, EMNRD

Subject: RE: [EXTERNAL] RE: Linda Nye 1A BGT Closure Notification

Date: Wednesday, June 25, 2025 9:04:24 AM

Attachments: <u>image001.png</u>

[**EXTERNAL EMAIL**]

Hey Brittany,

The GPS coordinates that I provided are not correct. The correct GPS coordinates are Lat: 36.80093 Long: -107.70368. I apologize for any inconvenience. Thank you for the correct coordinates.

From: Hall, Brittany, EMNRD <Brittany.Hall@emnrd.nm.gov>

Sent: Wednesday, June 25, 2025 9:58 AM

To: Chad Snell - (C) < Chad. Snell@harvestmidstream.com>

Cc: Enviro, OCD, EMNRD <OCD.Enviro@emnrd.nm.gov>; Stone, Joel, EMNRD

<Joel.Stone@emnrd.nm.gov>; Adeloye, Abiodun A <aadeloye@blm.gov>; jcraun@blm.gov; Monica
Smith <msmith@harvestmidstream.com>; Brooke Herb <bherb@ensolum.com>; Bratcher, Michael,
EMNRD <mike.bratcher@emnrd.nm.gov>; Barr, Leigh, EMNRD <leighp.barr@emnrd.nm.gov>; Wells,
Shelly, EMNRD <Shelly.Wells@emnrd.nm.gov>

Subject: RE: [EXTERNAL] RE: Linda Nye 1A BGT Closure Notification

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Good morning Chad,

Thank you for the notice but could you please verify the location of the BGT? The GPS coordinates OCD have on record are Lat: 36.80093 Long: -107.70368. The GPS coordinates provided in the notification (Lat: 36.8077 Long: -107.70407) place the BGT on the northern side of Hwy 173 and on the side of a hill.

Thank you,

Brittany Hall ● Environmental Field Compliance Supervisor

Environmental Field Compliance Group

EMNRD - Oil Conservation Division

1000 Rio Brazos Road | Aztec, NM 87410

505.517.5333 | Brittany.Hall@emnrd.nm.gov

http://www.emnrd.nm.gov/ocd/

Effective 12/1/2024: OCD has updated guidance on karst potential occurrence zones. This notice can be found at: https://www.emnrd.nm.gov/ocd/ocd-announcements-and-notifications/

under "2024 OCD ANNOUNCEMENTS AND NOTIFICATIONS".

The Digital C-141 guidance documents can be found at https://www.emnrd.nm.gov/ocd/ocd-forms/.

From: Chad Snell - (C) < <u>Chad.Snell@harvestmidstream.com</u>>

Sent: Wednesday, June 25, 2025 5:39 AM

To: Enviro, OCD, EMNRD < OCD. Enviro@emnrd.nm.gov >; Stone, Joel, EMNRD

<<u>Joel.Stone@emnrd.nm.gov</u>>; Adeloye, Abiodun A <<u>aadeloye@blm.gov</u>>; Craun, James (Nolan)

<<u>icraun@blm.gov</u>>

Cc: Monica Smith < msmith@harvestmidstream.com >; Brooke Herb < bherb@ensolum.com >

Subject: [EXTERNAL] RE: Linda Nye 1A BGT Closure Notification

Some people who received this message don't often get email from chad.snell@harvestmidstream.com. Learn.why this is important.

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Good Morning,

Harvest will be performing sampling activities for BGT closure at the Linda NYE 1A **(API: 30-045-22277, Sec: 20 Twn: 30N Rge: 8W Lat: 36.8077 Long: -107.70407)**. Sampling activities will take place on Monday June 30thth at 9:30am. Please let us know if you have any questions.

Thank you.

Chad Snell
Environmental Specialist
Harvest Four Corners, LLC
chad.snell@harvestmidstream.com
(505) 320-8621 (cell)



From: Chad Snell - (C)

Sent: Thursday, June 5, 2025 1:53 PM

To: ocd.enviro@emnrd.nm.gov; Joel.Stone@emnrd.nm.gov; Adeloye, Abiodun A

<aadeloye@blm.gov>; Craun, James (Nolan) <<u>jcraun@blm.gov</u>>

Cc: Monica Smith < msmith@harvestmidstream.com >; Brooke Herb < bherb@ensolum.com >

Subject: RE: Linda Nye 1A BGT Closure Notification

Closure activities will be postponed to a later date due to a scheduling conflict. Sorry for any inconvenience. I will send out another notification once closure activities are rescheduled. Please let me know if you have any questions.

Thank you.

From: Chad Snell - (C)

Sent: Monday, June 2, 2025 10:04 AM

To: ocd.enviro@emnrd.nm.gov; Joel.Stone@emnrd.nm.gov; Adeloye, Abiodun A

<aadeloye@blm.gov>; Craun, James (Nolan) <<u>jcraun@blm.gov</u>>

Cc: Monica Smith < msmith@harvestmidstream.com >; Brooke Herb < bherb@ensolum.com >


Subject: Linda Nye 1A BGT Closure Notification

Good morning,

Harvest will be performing sampling activities for BGT closure at the Linda NYE 1A **(API: 30-045-22277, Sec: 20 Twn: 30N Rge: 8W Lat: 36.8077 Long: -107.70407)**. Sampling activities will take place on Thursday June 5th at 10:30am. Please let us know if you have any questions.

Thank you.

Chad Snell
Environmental Specialist
Harvest Four Corners, LLC
chad.snell@harvestmidstream.com
(505) 320-8621 (cell)
HARVEST



While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please

immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.



APPENDIX C

Soil Sample Collection Field Forms

Harvest Midstream

MILLER	MILDSTREA	M			
		ON-	SITE FORM	Л	
Facility N	ame_Lind	a NYE 1A	Lattituda 36 80	197	(4) > 260
1.00	11 1	475 16611	C1_1. / / /	Л	A1
Contracto	rs On-Site	Siers oil Field	Time On Site 7	Cou	inty Jan Joan
Land Use	(Range / Re	esidential / Tribe BLA	1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \) Recovere	d_W/A_(Gallons)
n		esidential / Tribe BLA	Spill Area _	x	x deep
w **	e)	1	-	;
s		/		1	1x x
					(x) 1
	11		meser)	11	12 x
l / ,	well	y.	I meser Bat	11 1_	1
	*		961	<u> </u>	
1 (150	1	
			1 8 3		7
	Comp	(00)	20	1 284	f
		AGTS		ر ا	
Site Diagra	m			1 1	
NM	000	Was onsite	to with ce	<u> </u>	
, , ,		0 0 0,12	0 0 1(1/25)	Sampling	ş
Comments					
- Comments					
Time	Sample #	Sample Description	amples		
0			Characteristics	OVM (ppm)	Analysis Requested
9:35cm		Composite, BayT	C/cv. Brown. No	Mal	971010 41111
		,	47 4 17 17 17 17	2201	881, Rols, Chloride

e 6-36-25
te

Name (Signature) 1115 Company JAKD



APPENDIX D

Photographic Log

Photographic Log Lateral M2 BGT Rio Arriba County, New Mexico Harvest Four Corners, LLC

Photograph 1

Photograph looking southeast after the BGT was removed.



Photograph 2

Photograph looking southeast of the backfilled pit.





APPENDIX E

Laboratory Analytical Report

ANALYTICAL REPORT

PREPARED FOR

Attn: Monica Smith Harvest 1755 Arroyo Dr. Bloomfield, New Mexico 87413

Generated 7/8/2025 2:38:38 PM

JOB DESCRIPTION

Linda NYE 1A

JOB NUMBER

885-27861-1

Eurofins Albuquerque 4901 Hawkins NE Albuquerque NM 87109

Eurofins Albuquerque

Job Notes

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Environment Testing South Central, LLC Project Manager.

Authorization

Generated 7/8/2025 2:38:38 PM

Authorized for release by Michelle Garcia, Project Manager michelle.garcia@et.eurofinsus.com (505)345-3975

Page 2 of 14 7/8/2025

3

4

5

7

8

9

10

11

Laboratory Job ID: 885-27861-1

Client: Harvest Project/Site: Linda NYE 1A

Table of Contents

Cover Page	1
Table of Contents	3
Definitions/Glossary	4
Case Narrative	5
Client Sample Results	6
QC Sample Results	7
QC Association Summary	10
Lab Chronicle	11
Certification Summary	12
Chain of Custody	13
Receipt Checklists	14

3

J

4

6

8

9

Definitions/Glossary

Client: Harvest Job ID: 885-27861-1

Project/Site: Linda NYE 1A

001-1

Glossary

Abbreviation These commonly used abbreviations may or may not be present in this report.

Listed under the "D" column to designate that the result is reported on a dry weight basis

%R Percent Recovery

CFL Contains Free Liquid
CFU Colony Forming Unit
CNF Contains No Free Liquid

DER Duplicate Error Ratio (normalized absolute difference)

Dil Fac Dilution Factor

DL Detection Limit (DoD/DOE)

DL, RA, RE, IN Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample

DLC Decision Level Concentration (Radiochemistry)

EDL Estimated Detection Limit (Dioxin)

LOD Limit of Detection (DoD/DOE)

LOQ Limit of Quantitation (DoD/DOE)

MCL EPA recommended "Maximum Contaminant Level"

MDA Minimum Detectable Activity (Radiochemistry)

MDC Minimum Detectable Concentration (Radiochemistry)

MDL Method Detection Limit
ML Minimum Level (Dioxin)
MPN Most Probable Number
MQL Method Quantitation Limit

NC Not Calculated

ND Not Detected at the reporting limit (or MDL or EDL if shown)

 NEG
 Negative / Absent

 POS
 Positive / Present

 PQL
 Practical Quantitation Limit

PRES Presumptive
QC Quality Control

RER Relative Error Ratio (Radiochemistry)

RL Reporting Limit or Requested Limit (Radiochemistry)

RPD Relative Percent Difference, a measure of the relative difference between two points

TEF Toxicity Equivalent Factor (Dioxin)
TEQ Toxicity Equivalent Quotient (Dioxin)

TNTC Too Numerous To Count

Eurofins Albuquerque

2

_

5

6

o

9

10

Case Narrative

Client: Harvest Job ID: 885-27861-1

Project: Linda NYE 1A

Job ID: 885-27861-1 Eurofins Albuquerque

Job Narrative 885-27861-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers and/or narrative comments are included to explain any exceptions, if applicable.

- Matrix QC may not be reported if insufficient sample is provided or site-specific QC samples were not submitted. In these
 situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise
 specified in the method.
- Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

Receipt

The sample was received on 7/1/2025 7:10 AM. Unless otherwise noted below, the sample arrived in good condition, and, where required, properly preserved and on ice. The temperature of the cooler at receipt time was 4.5°C.

Gasoline Range Organics

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

GC VOA

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Diesel Range Organics

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

HPLC/IC

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Eurofins Albuquerque

-

3

4

5

7

0

4.6

Client Sample Results

Client: Harvest Job ID: 885-27861-1

Project/Site: Linda NYE 1A

Client Sample ID: BGT Bottom

Lab Sample ID: 885-27861-1 Date Collected: 06/30/25 09:35

Matrix: Solid

Date Received: 07/01/25 07:10

Chloride

Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Gasoline Range Organics [C6 - C10]	ND		4.8	mg/Kg		07/02/25 13:14	07/04/25 08:10	1
Surrogate	%Recovery	Qualifier	Limits			Prepared	Analyzed	Dil Fac
4-Bromofluorobenzene (Surr)	87		15 - 150			07/02/25 13:14	07/04/25 08:10	
Method: SW846 8021B - Volatile	Organic Comp	ounds (GC))					
Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	ND		0.024	mg/Kg		07/02/25 13:14	07/04/25 08:10	1
Ethylbenzene	ND		0.048	mg/Kg		07/02/25 13:14	07/04/25 08:10	1
Toluene	ND		0.048	mg/Kg		07/02/25 13:14	07/04/25 08:10	1
Xylenes, Total	ND		0.097	mg/Kg		07/02/25 13:14	07/04/25 08:10	1
Surrogate	%Recovery	Qualifier	Limits			Prepared	Analyzed	Dil Fac
4-Bromofluorobenzene (Surr)	87		15 - 150			07/02/25 13:14	07/04/25 08:10	1
Method: SW846 8015M/D - Diese	I Range Organ	ics (DRO) (GC)					
Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Diesel Range Organics [C10-C28]	ND		9.6	mg/Kg		07/07/25 11:56	07/07/25 21:52	1
Motor Oil Range Organics [C28-C40]	ND		48	mg/Kg		07/07/25 11:56	07/07/25 21:52	1
Surrogate	%Recovery	Qualifier	Limits			Prepared	Analyzed	Dil Fac
Di-n-octyl phthalate (Surr)	81		62 - 134			07/07/25 11:56	07/07/25 21:52	1
Method: EPA 300.0 - Anions, Ion	Chromatograp	hy						

60

mg/Kg

ND

07/07/25 10:24 07/07/25 12:26

QC Sample Results

Client: Harvest Job ID: 885-27861-1

Project/Site: Linda NYE 1A

Lab Sample ID: MB 885-29462/1-A Client Sample ID: Method Blank

Matrix: Solid

Analysis Batch: 29561

Prep Type: Total/NA

Prep Batch: 29462

Analyte Result Qualifier RLUnit D Prepared Analyzed Dil Fac Gasoline Range Organics [C6 - C10] ND 5.0 mg/Kg 07/02/25 13:14 07/04/25 07:47

MB MB

мв мв

Surrogate %Recovery Qualifier Limits Prepared Analyzed Dil Fac 4-Bromofluorobenzene (Surr) 89 15 - 150 07/02/25 13:14 07/04/25 07:47

Lab Sample ID: LCS 885-29462/2-A Client Sample ID: Lab Control Sample

Matrix: Solid

Analysis Batch: 29561

Spike LCS LCS Prep Type: Total/NA

Prep Batch: 29462

%Rec Analyte Added Result Qualifier Unit %Rec Limits 25.0 22.8 91 70 - 130 Gasoline Range Organics [C6 mg/Kg

C10]

LCS LCS

%Recovery Qualifier Limits Surrogate 4-Bromofluorobenzene (Surr) 183 15 - 150

Method: 8015M/D - Gasoline Range Organics (GRO) (GC)

Lab Sample ID: 885-27861-1 MS Client Sample ID: BGT Bottom

Matrix: Solid

Analysis Batch: 29561

Prep Type: Total/NA

Prep Batch: 29462

Sample Sample Spike MS MS Result Qualifier Added Result Qualifier Analyte Unit %Rec Limits 24.3 22.9 94 70 - 130 Gasoline Range Organics [C6 -ND mg/Kg

C10]

MS MS

Surrogate %Recovery Qualifier Limits 184 15 - 150

4-Bromofluorobenzene (Surr)

Lab Sample ID: 885-27861-1 MSD

Matrix: Solid

Analysis Batch: 29561

Gasoline Range Organics [C6 -

Client Sample ID: BGT Bottom

70 - 130

99

Prep Type: Total/NA Prep Batch: 29462

20

Sample Sample MSD MSD RPD Spike %Rec Result Qualifier babbA Qualifier Limits RPD Limit Analyte Result Unit %Rec

24.0

mg/Kg

24.2

C10]

MSD MSD

ND

%Recovery Surrogate Qualifier Limits 15 - 150 4-Bromofluorobenzene (Surr) 183

Method: 8021B - Volatile Organic Compounds (GC)

Lab Sample ID: MB 885-29462/1-A

Matrix: Solid

Released to Imaging: 9/18/2025 1:33:44 PM

Client Sample ID: Method Blank

Prep Type: Total/NA Prep Batch: 29462

Analysis Batch: 29562

	мв мы	IB .					
Analyte	Result Qu	ualifier RL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	ND	0.025	mg/Kg		07/02/25 13:14	07/04/25 07:47	1
Ethylbenzene	ND	0.050	mg/Kg		07/02/25 13:14	07/04/25 07:47	1
Toluene	ND	0.050	mg/Kg		07/02/25 13:14	07/04/25 07:47	1

Client: Harvest Job ID: 885-27861-1

Project/Site: Linda NYE 1A

Method: 8021B - Volatile Organic Compounds (GC) (Continued)

Lab Sample ID: MB 885-29462/1-A Matrix: Solid

Analysis Batch: 29562

Client Sample ID: Method Blank

Prep Type: Total/NA Prep Batch: 29462

Analyte	Result Qu	ualifier RL	Unit	D	Prepared	Analyzed	Dil Fac
Xylenes, Total	ND	0.10	mg/Kg		07/02/25 13:14	07/04/25 07:47	1

MB MB

MB MB

 Surrogate
 %Recovery
 Qualifier
 Limits
 Prepared
 Analyzed
 Dil Fac

 4-Bromofiuorobenzene (Surr)
 88
 15 - 150
 07/02/25 13:14
 07/04/25 07:47
 1

Lab Sample ID: LCS 885-29462/3-A Client Sample ID: Lab Control Sample

Matrix: Solid

Analysis Batch: 29562

Prep Type: Total/NA

Prep Batch: 29462

	Spike	LCS	LCS				%Rec	
Analyte	Added	Result	Qualifier	Unit	D	%Rec	Limits	
Benzene	1.00	1.01		mg/Kg		101	70 - 130	
Ethylbenzene	1.00	0.977		mg/Kg		98	70 - 130	
Toluene	1.00	0.989		mg/Kg		99	70 - 130	
Xylenes, Total	3.00	3.02		mg/Kg		101	70 - 130	

LCS LCS

MB MB

Surrogate%RecoveryQualifierLimits4-Bromofluorobenzene (Surr)9215 - 150

Method: 8015M/D - Diesel Range Organics (DRO) (GC)

Lab Sample ID: MB 885-29599/1-A

Matrix: Solid

Analysis Batch: 29570

Client Sample ID: Method Blank

Prep Type: Total/NA

Prep Batch: 29599

Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Diesel Range Organics [C10-C28]	ND		10	mg/Kg		07/07/25 11:56	07/07/25 17:17	1
Motor Oil Range Organics [C28-C40]	ND		50	mg/Kg		07/07/25 11:56	07/07/25 17:17	1
	МВ	МВ						

 Surrogate
 %Recovery
 Qualifier
 Limits
 Prepared
 Analyzed
 Dil Fac

 Di-n-octyl phthalate (Surr)
 79
 62 - 134
 07/07/25 11:56
 07/07/25 17:17
 1

Lab Sample ID: LCS 885-29599/2-A

Matrix: Solid

Analysis Batch: 29570

Client Sample ID: Lab Control Sample

Prep Type: Total/NA Prep Batch: 29599

Spike LCS LCS %Rec Analyte Added Result Qualifier Limits Unit D %Rec 50.0 46.4 93 Diesel Range Organics mg/Kg 51 - 148

[C10-C28]

 Surrogate
 %Recovery Di-n-octyl phthalate (Surr)
 83
 Qualifier Limits 62 - 134

Eurofins Albuquerque

2

4

6

0

9

QC Sample Results

Spike

Added

49.9

Client: Harvest Job ID: 885-27861-1

> MS MS

31.7

Result Qualifier

Unit

mg/Kg

Project/Site: Linda NYE 1A

Method: 8015M/D - Diesel Range Organics (DRO) (GC) (Continued)

Lab Sample ID: 885-27861-1 MS **Matrix: Solid**

Lab Sample ID: 885-27861-1 MSD

Analysis Batch: 29570

Diesel Range Organics

Client Sample ID: BGT Bottom

Prep Type: Total/NA

Prep Batch: 29599

%Rec Limits 64 44 - 136

[C10-C28]

Analyte

MS MS

ND

Sample Sample

Result Qualifier

%Recovery Limits Surrogate Qualifier 62 - 134 Di-n-octyl phthalate (Surr) 88

Client Sample ID: BGT Bottom

Prep Type: Total/NA

Prep Batch: 29599

RPD

Sample Sample Spike MSD MSD Result Qualifier Analyte babbA Result Qualifier %Rec Limits RPD Limit Unit D Diesel Range Organics ND 47.3 29.5 mg/Kg 62 44 - 136 32

[C10-C28]

Matrix: Solid

Analysis Batch: 29570

MSD MSD

Surrogate %Recovery Qualifier Limits Di-n-octyl phthalate (Surr) 88 62 - 134

Method: 300.0 - Anions, Ion Chromatography

Lab Sample ID: MB 885-29584/1-A

Matrix: Solid

Analysis Batch: 29591

Client Sample ID: Method Blank

Prep Type: Total/NA

Prep Batch: 29584

мв мв Result Qualifier RL Unit Dil Fac Analyte D Prepared Analyzed 1.5 07/07/25 11:37 Chloride 07/07/25 10:24 ND mg/Kg

Lab Sample ID: LCS 885-29584/2-A

Matrix: Solid

Analysis Batch: 29591

Client Sample ID: Lab Control Sample

Prep Type: Total/NA Prep Batch: 29584

LCS LCS Spike Analyte Added Result Qualifier Unit %Rec Limits Chloride 15.0 14.6 mg/Kg 97 90 - 110

QC Association Summary

Client: Harvest

Job ID: 885-27861-1 Project/Site: Linda NYE 1A

GC VOA

Prep Batch: 29462

Lab Sample ID 885-27861-1 MB 885-29462/1-A LCS 885-29462/2-A	Client Sample ID BGT Bottom Method Blank Lab Control Sample	Prep Type Total/NA Total/NA Total/NA	Matrix Solid Solid Solid	Method 5030C 5030C 5030C	Prep Batch
LCS 885-29462/3-A	Lab Control Sample	Total/NA	Solid	5030C	
885-27861-1 MS	BGT Bottom	Total/NA	Solid	5030C	
885-27861-1 MSD	BGT Bottom	Total/NA	Solid	5030C	

Analysis Batch: 29561

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
885-27861-1	BGT Bottom	Total/NA	Solid	8015M/D	29462
MB 885-29462/1-A	Method Blank	Total/NA	Solid	8015M/D	29462
LCS 885-29462/2-A	Lab Control Sample	Total/NA	Solid	8015M/D	29462
885-27861-1 MS	BGT Bottom	Total/NA	Solid	8015M/D	29462
885-27861-1 MSD	BGT Bottom	Total/NA	Solid	8015M/D	29462

Analysis Batch: 29562

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
885-27861-1	BGT Bottom	Total/NA	Solid	8021B	29462
MB 885-29462/1-A	Method Blank	Total/NA	Solid	8021B	29462
LCS 885-29462/3-A	Lab Control Sample	Total/NA	Solid	8021B	29462

GC Semi VOA

Analysis Batch: 29570

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
885-27861-1	BGT Bottom	Total/NA	Solid	8015M/D	29599
MB 885-29599/1-A	Method Blank	Total/NA	Solid	8015M/D	29599
LCS 885-29599/2-A	Lab Control Sample	Total/NA	Solid	8015M/D	29599
885-27861-1 MS	BGT Bottom	Total/NA	Solid	8015M/D	29599
885-27861-1 MSD	BGT Bottom	Total/NA	Solid	8015M/D	29599

Prep Batch: 29599

Lab Sample ID 885-27861-1	Client Sample ID BGT Bottom	Prep Type Total/NA	Matrix Solid	Method SHAKE	Prep Batch
MB 885-29599/1-A	Method Blank	Total/NA	Solid	SHAKE	
LCS 885-29599/2-A	Lab Control Sample	Total/NA	Solid	SHAKE	
885-27861-1 MS	BGT Bottom	Total/NA	Solid	SHAKE	
885-27861-1 MSD	BGT Bottom	Total/NA	Solid	SHAKE	

HPLC/IC

Prep Batch: 29584

Lab Sample ID 885-27861-1	Client Sample ID BGT Bottom	Prep Type Total/NA	Matrix Solid	Method	Prep Batch
MB 885-29584/1-A	Method Blank	Total/NA	Solid	300_Prep 300_Prep	
LCS 885-29584/2-A	Lab Control Sample	Total/NA	Solid	300_Prep	

Analysis Batch: 29591

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
885-27861-1	BGT Bottom	Total/NA	Solid	300.0	29584
MB 885-29584/1-A	Method Blank	Total/NA	Solid	300.0	29584
LCS 885-29584/2-A	Lab Control Sample	Total/NA	Solid	300.0	29584

Lab Chronicle

Client: Harvest Job ID: 885-27861-1

Project/Site: Linda NYE 1A

Client Sample ID: BGT Bottom

Lab Sample ID: 885-27861-1 Date Collected: 06/30/25 09:35

Matrix: Solid

Date Received: 07/01/25 07:10

	Batch	Batch		Dilution	Batch			Prepared
Prep Type	Type	Method	Run	Factor	Number	Analyst	Lab	or Analyzed
Total/NA	Prep	5030C			29462	JP	EET ALB	07/02/25 13:14
Total/NA	Analysis	8015M/D		1	29561	JP	EET ALB	07/04/25 08:10
Total/NA	Prep	5030C			29462	JP	EET ALB	07/02/25 13:14
Total/NA	Analysis	8021B		1	29562	JP	EET ALB	07/04/25 08:10
Total/NA	Prep	SHAKE			29599	EM	EET ALB	07/07/25 11:56
Total/NA	Analysis	8015M/D		1	29570	EM	EET ALB	07/07/25 21:52
Total/NA	Prep	300_Prep			29584	MA	EET ALB	07/07/25 10:24
Total/NA	Analysis	300.0		20	29591	MA	EET ALB	07/07/25 12:26

Laboratory References:

EET ALB = Eurofins Albuquerque, 4901 Hawkins NE, Albuquerque, NM 87109, TEL (505)345-3975

Accreditation/Certification Summary

Client: Harvest Job ID: 885-27861-1

Project/Site: Linda NYE 1A

Laboratory: Eurofins Albuquerque

Unless otherwise noted, all analytes for this laboratory were covered under each accreditation/certification below.

Authority	Progr	ram	Identification Number	Expiration Date	
New Mexico			NM9425, NM0901	02-27-26	
• •	are included in this report, b	ut the laboratory is not certif	ied by the governing authority. This lis	st may include analytes	
Analysis Method	Prep Method	Matrix	Analyte		
300.0	300_Prep	Solid Chloride	Chloride		
8015M/D	5030C	Solid	Gasoline Range Organics	[C6 - C10]	
8015M/D	SHAKE	Solid	Diesel Range Organics [C	:s [C10-C28]	
8015M/D	SHAKE	Solid	Motor Oil Range Organics	[C28-C40]	
8021B	5030C	Solid	Benzene		
8021B	5030C	Solid	Ethylbenzene		
8021B	5030C	Solid	Toluene		
8021B	5030C	Solid	Xylenes, Total		
Oregon	NELA	ΛP	NM100001	02-26-26	

Page 13 of 14

Date

Client:

Phone #:

□ Standard

□ NELAC

Login Sample Receipt Checklist

Client: Harvest Job Number: 885-27861-1

Login Number: 27861 List Source: Eurofins Albuquerque

List Number: 1

Creator: Casarrubias, Tracy

Creator: Casarrubias, Tracy		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>N/A</td> <td></td>	N/A	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	N/A	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 503307

CONDITIONS

Operator:	OGRID:
Harvest Four Corners, LLC	373888
1755 Arroyo Dr	Action Number:
Bloomfield, NM 87413	503307
	Action Type:
	[C-144] Below Grade Tank Plan (C-144B)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	Upon the cessation of all production operations in the area associated with well API 30-045-22277 (Linda Nye #001A), the operator shall complete the requirements of 19.15.17.13 NMAC for the area associated with this below-grade tank and notify the OCD when restoration, reclamation, and re-vegetation are complete.	9/18/2025