

Well Name: GALLEGOS FEDERAL 26-13-1**Well Location:** T26N / R13W / SEC 1 / NWNE / 36.5221 / -108.16666**County or Parish/State:** SAN JUAN / NM**Well Number:** 1**Type of Well:** OTHER**Allottee or Tribe Name:****Lease Number:** NMSF080238A**Unit or CA Name:****Unit or CA Number:****US Well Number:** 3004528881**Operator:** HILCORP ENERGY COMPANY

Subsequent Report

Sundry ID: 2886233**Type of Submission:** Subsequent Report**Type of Action:** Mechanical Integrity Test**Date Sundry Submitted:** 12/10/2025**Time Sundry Submitted:** 09:53**Date Operation Actually Began:** 12/08/2025

Actual Procedure: A MIT was performed on the subject well on 12/8/2025. PT to 580# for 30 min, test good. Witnessed by Rooster Foster with NMOCD. Please see attached chart. Hilcorp requests NMOCD's permission to extend the Temporarily Abandoned status to review for future potential.

SR Attachments

Actual Procedure

Gallegos_Fed_26_13_1_1_SR_MIT_BLM_Submitted_20251210095333.pdf

Well Name: GALLEGOS FEDERAL 26-13-1**Well Location:** T26N / R13W / SEC 1 / NWNE / 36.5221 / -108.16666**County or Parish/State:** SAN JUAN / NM**Well Number:** 1**Type of Well:** OTHER**Allottee or Tribe Name:****Lease Number:** NMSF080238A**Unit or CA Name:****Unit or CA Number:****US Well Number:** 3004528881**Operator:** HILCORP ENERGY COMPANY

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: PRISCILLA SHORTY**Signed on:** DEC 10, 2025 09:53 AM**Name:** HILCORP ENERGY COMPANY**Title:** Regulatory Technician**Street Address:** 382 ROAD 3100**City:** AZTEC**State:** NM**Phone:** (505) 324-5188**Email address:** PSHORTY@HILCORP.COM

Field

Representative Name:**Street Address:****City:****State:****Zip:****Phone:****Email address:**

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK**BLM POC Title:** Petroleum Engineer**BLM POC Phone:** 5055647742**BLM POC Email Address:** krennick@blm.gov**Disposition:** Accepted**Disposition Date:** 12/11/2025**Signature:** Kenneth Rennick



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 12-8-25 Operator H.I. Corp API # 30-045-28881

Property Name Gallegos Fed 26-13-1 Well # 1 Location: Unit B Sec 1 Twn 26N Rge 13W

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well ☒ (Y/N): _____ TA Expires: _____

Casing Pres. 0 _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 _____ Tbg. Inj. Pres. _____
Tubing Pres. 0 _____
Int. Casing Pres. NP _____

Pressured annulus up to 580 psi. for 30 mins. Test passed failed

REMARKS:

Cement Ret @ 1116'
Pressured up to ~~500~~ 580 psi held until last 15 min of test
fell to 576

By [Signature]
(Operator Representative)

Witness [Signature] OLD
(NMOCD)

Wellbite Supervisor
(Position)

Revised 02-11-02



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-8-25 Operator Hilcorp API #30-0 45-28881
Property Name Gallegos fed ^{26-B-1} Well No. 26-1 Location: Unit B Section 01 Township 26^N Range 18^W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	0		
10 min	0	0	0		
15 min	0	0	0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <input checked="" type="checkbox"/>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

BH had nothing on it

By Tel Baird

Witness Roger Foster OCD

Wellsite Supervisor
(Position)

E-mail address tel.baird@hilcorp.com






Current Schematic - Version 3

Well Name: GALLEGOS FEDERAL 26 13 1 #1

API / UWI 3004528881	Surface Legal Location T26N-R13W-S01	Field Name Basin Fruitland Coal	Route 0600	State/Province NEW MEXICO	Well Configuration Type Vertical
Ground Elevation (ft) 5,948.00	Original KB/RT Elevation (ft) 5,951.44	Tubing Hanger Elevation (ft)	RKB to GL (ft) 3.44	KB-Casing Flange Distance (ft)	KB-Tubing Hanger Distance (ft)
Tubing Strings					
Run Date 2/2/2016 11:00	Set Depth (ftKB) 1,099.02	String Max Nominal OD (in) 2 3/8	String Min Nominal ID (in) 2.00	Weight/Length (lb/ft) 4.70	Original Spud Date 12/26/1992 00:00

Original Hole, GALLEGOS FEDERAL 26 13 1 #1 [Vertical]



Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 533966

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 533966
	Action Type: [C-103] Sub. Temporary Abandonment (C-103U)

CONDITIONS

Created By	Condition	Condition Date
andrew.fordyce	None	12/12/2025