



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-5-25 Operator Kimberly API #30-0 39-22317

Property Name Seal Well No. 3E Location: Unit E Section 35 Township 25N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 175 Intermediate _____ Casing 220 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME					
5 min	<u>0</u>		<u>220</u>		
10 min	<u>0</u>		<u>220</u>		
15 min	<u>0</u>		<u>220</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	_____
Surges	_____
Down to Nothing	_____
Nothing	_____
Gas	_____
Gas & Water	_____
Water	_____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Kimberly
(Position) Rumper

Witness _____

E-mail address _____

Santa Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 471291

CONDITIONS

Operator: KIMBELL OIL CO OF TEXAS 777 Taylor Street Ft Worth, TX 76102	OGRID: 12683
	Action Number: 471291
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025