



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 11-10-25 Operator Simcoe, LLC API #30-04508335


Property Name Marscow Gas Com Well No. 1 Location: Unit F Section 15 Township 24 Range 18

Well Status(Shut-In or Producing) Initial PSI: Tubing 79 Intermediate 114 Casing 80 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME					
5 min	0	90			
10 min	0	90			
15 min	0	90	N	A	
20 min	0	90			
25 min	0	90			
30 min	0	90			

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 114

REMARKS:

Manifold used 1"

5 min Shut in, slight puff

By Sean

Witness Randy Foster

Field Tech

(Position)

E-mail address sean@agaslab.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 525506

CONDITIONS

Operator: SIMCOE LLC 1199 Main Ave., Suite 101 Durango, CO 81301	OGRID: 329736
	Action Number: 525506
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	According to the well file this well should be tested in a year and then can be decided to return to regular testing. The well file shows the last test was done in 1/25. Monica Kueling from OCD stated there needed to be a 6 month and year test.	12/31/2025