



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-19-21 Operator _____ API #30-0 45-24159

Property Name South east cha Well No. 36 Location: Unit 8 Section 8 Township 28N Range 13W
cha

Well Status(Shut-In or Producing) Initial PSI: Tubing 80 Intermediate _____ Casing 52 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead		INTERM	BRADENHEAD		INTERMEDIATE
TIME	BH	Int	Csg	Int	Csg	
5 min			52			
10 min						
15 min						
20 min						
25 min						
30 min			52			

Steady Flow	_____	_____
Surges	_____	_____
Down to Nothing	✓	NS
Nothing	✓	_____
Gas	_____	_____
Gas & Water	_____	_____
Water	_____	_____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE 10

REMARKS:

By _____

Witness _____

(Position)

E-mail address _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 525199

CONDITIONS

Operator: PETRO MEX LLC P.O. Box 6724 Farmington, NM 87499	OGRID: 236452
	Action Number: 525199
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	1/5/2026