

District 1
 1625 N French Dr, Hobbs, NM 88240
 Phone (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-32026
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No 126H

1 Surface Location									
UL - Lot L	Section 1	Township 18S	Range 34E		Feet from 1980	N/S Line FSL	Feet From 1308	E/W Line FWL	County LEA

Well Status										
TA'D WELL YES	<input checked="" type="radio"/> NO	YES	SHUT-IN <input checked="" type="radio"/> NO	INJ	INJECTOR	SWD	<input checked="" type="radio"/> OIL	PRODUCER	GAS	DATE 2-19-25

OBSERVED DATA

	(A)Surface	(B)Intermf(1)	(C)Intermf(2)	(D)Prod Csg	(E)Tubing
Pressure	\emptyset			120	300
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR ___ GAS ___ Type of Fluid Injected for Workload if applicable
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Joe Math</i>	OIL CONSERVATION DIVISION
Printed name: Joe Math	Entered into RBDMS
Title: LDone Operator	Re-test
E-mail Address: jmath@ctfieldsvcs.com	
Date: 2-19-25	Phone: 682.352.4942
Witness	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455806

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 455806
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/28/2026