

District 1
 1625 N French Dr., Hobbs, NM 88240
 Phone (575) 393-6101 Fax (575) 393-0120

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC	API Number 30-025-02220
Property Name STATE 35 UNIT	Well No 019

1. Surface Location									
UL - Lot K	Section 35	Township 17S	Range 34E	Feet from 1980	N/S Line FSL	Feet From 1980	E/W Line FWL	County LEA	

Well Status										
TA'D WELL YES	<input checked="" type="radio"/> NO	SHUT-IN YES	<input checked="" type="radio"/> NO	INJ	INJECTOR	SWD	<input checked="" type="radio"/> OIL	PRODUCER	GAS	DATE 3-5-2025

OBSERVED DATA

	(A)Surface	(B)Intermf(1)	(C)Intermf(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	35"	35"
Flow Characteristics					
Puff	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	CO2 WTR ___ GAS ___ Type of Fluid Injected for Waterflood if apples
Steady Flow	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	
Surges	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	
Down to nothing	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	
Gas or Oil	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	
Water	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>John Stevenson</i>	OIL CONSERVATION DIVISION
Printed name: John STEVENSON	Entered into RBDMS
Title: Foreman	Re-test
E-mail Address:	
Date: 3-5-2025	Phone: 1-682-269-0257
	Witness

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455881

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 455881
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	2/2/2026