

Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
Maljamar AGI#1 30-025-40420
Maljamar AGI#2 30-025-42628
5. Indicate Type of Lease
STATE [] FEE [] FEDERAL [X]
6. State Oil & Gas Lease No.
NMLC029509A
7. Lease Name or Unit Agreement Name
Maljamar AGI
8. Well Number
#1 and #2
9. OGRID Number
221115
10. Pool name or Wildcat
AGI: Wolfcamp
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
AGI#1 4,016 (GR) AGI#2 4,019 (GR)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [] Other: Acid Gas Injection Well [X]
2. Name of Operator
Frontier Field Services, LLC
3. Address of Operator
303 Veterans Airpark Lane, Suite 2000
Midland, TX 797505
4. Well Location AGI#1 Unit Letter O : 130 feet from the SOUTH line and 1,813 feet from the EAST line
AGI#2 Unit Letter O : 400 feet from the SOUTH line and 2,100 feet from the EAST line
Section 21 Township 17S Range 32E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
AGI#1 4,016 (GR) AGI#2 4,019 (GR)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: 4Q 2025 Report [X]
per NMOCC Order R-13443

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This represents the 4Q2025 report for the AGI#1 and AGI#2 dual well AGI system at Frontier Field Services LLC's Maljamar Gas Plant pursuant to the quarterly reporting required under NMOCC Order R-13443. AGI#2 has bottom-hole PT sensors which provide data on reservoir pressure and temperature that have been performing as designed and providing insights into reservoir behavior. This report includes an analysis of the surface and bottom-hole data from AGI#2 and is also the 4Q report for the two-well system, as required under the order referenced above.

For 4Q2025, the flow from the plant was sent to both AGI#1 and AGI#2. When both wells are in operation, flow is kept constant at about 1.25 MMSCFD to AGI #2 while allowing AGI #1 to take the fluctuations in overall plant flow (see Figure 1). Average flow rate for the AGI #1 during the entire reporting period was 442 MSCFD. Average flow rate for the AGI #2 for the entire period was 1090 MSCFD. The surface injection parameters for both wells are shown on Figures 2 and 3, respectively. These two figures show the correlative behavior of injection pressure, injection temperature and annular pressure when both wells are operating and clearly demonstrate the continued integrity of both wells. During the period AGI #1 and AGI #2 showed average injection pressures of 2,372 psig and 2,271 psig, average injection temperatures of 91°F and 100°F and average surface annular pressures of 613 psig and 257 psig, respectively (see Figures 2 and 3). AGI #2 bottom-hole pressure and temperature for the entire period averaged 5064 psig and 123°F, respectively (see Figure 4). Finally, during the period the differential pressure (surface injection pressure vs. annular pressure) for AGI #1 averaged 1,759 psig, and 2,014 psig for AGI #2 (see Figure 5). The overall period average bottom-hole pressure values of 5064 psig and temperature of 123°F are reflective of current actual conditions in the reservoir and demonstrate ongoing favorable reservoir conditions. All of the graphs in Figures 1-5 further confirm the continued integrity of both Maljamar AGI#1 and Maljamar AGI#2, and the overall analysis demonstrates that both wells are fully in compliance with all applicable requirements of the NMOCC orders governing operation of this AGI system.

SIGNATURE Sebastian Orozco
Type or print name Sebastian Orozco
TITLE Environmental Specialist
E-mail address: sorozco@kinetik.com
DATE 2/10/2026
PHONE: 619-721-4813
APPROVED BY:
TITLE
DATE
Conditions of Approval (if any):

Figure 1: Maljamar AGI #1 and #2 Injection Rates




Figure 2: Maljamar AGI #1 Surface Injection Parameters







Figure 3: Maljamar AGI #2 Surface Injection Parameters







Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oecd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 552239

CONDITIONS

Operator: FRONTIER FIELD SERVICES, LLC 303 Veterans Airpark Lane Midland, TX 79705	OGRID: 221115
	Action Number: 552239
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
anthony.harris	None	2/17/2026