

LOGMAN'S TATE #2



Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS

Action 570546

**DEFINITIONS**

|  |   |
|--|---|
| Operator:<br>RILEY PERMIAN OPERATING COMPANY, LLC<br>29 E Reno Avenue<br>Oklahoma City, OK 73104 | OGRID:<br>372290  |
|  | Action Number:<br>570546                                |
|  | Action Type:<br>[C-103] Sub. Release After P&A (C-103Q) |

**DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 570546

**QUESTIONS**

|  |   |
|--|---|
| Operator:<br>RILEY PERMIAN OPERATING COMPANY, LLC<br>29 E Reno Avenue<br>Oklahoma City, OK 73104 | OGRID:<br>372290  |
|  | Action Number:<br>570546                                |
|  | Action Type:<br>[C-103] Sub. Release After P&A (C-103Q) |

**QUESTIONS**

|   |  |
|---|--|
| <b>Subsequent Report of: Location Ready For OCD Inspection After P&amp;A</b>  |  |
| Was this the last remaining or only well on the location  | No   |
| Are there any abandoned pipelines that are going to remain on the location  | No   |
| Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location | Yes  |
| If any production equipment or structure is to remain on the location, please specify   | Well shares pad with battery associated with other active wells in the area. Well also shares pad with other active well from another operator: BRAD STATE #004 (30-015-40621) |

**Site Evaluation**

Please answer all the questions in this group.

|   |   |
|---|---|
| Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan | Yes   |
| Have the rat hole and cellar been filled and leveled  | Yes   |
| Have the cathodic protection holes been properly abandoned  | Yes   |
| Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete                      | Yes   |
| The (concrete-set) steel marker shows:<br><i>Must attach marker photograph(s). *</i>  | <b><u>THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.</u></b> |
| Has the location been leveled as nearly as possible to original ground contour  | Yes   |
| Have all the required pipelines and other production equipment been cleared   | Yes   |
| Has all the required junk and trash been cleared from the location  | Yes   |
| Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level                | Yes   |
| Have all the required metal bolts and other materials have been removed   | Yes   |
| <b>Poured onsite concrete bases do not have to be removed.</b>  |   |
| Have all the the required portable bases been removed   | Yes   |
| Have all other environmental concerns have been addressed as per OCD rules  | Yes   |
| If any environmental concerns remain on the location, please specify  | Not answered.   |

\* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 570546

**QUESTIONS (continued)**

|  |   |
|--|---|
| Operator:<br>RILEY PERMIAN OPERATING COMPANY, LLC<br>29 E Reno Avenue<br>Oklahoma City, OK 73104 | OGRID:<br>372290  |
|  | Action Number:<br>570546                                |
|  | Action Type:<br>[C-103] Sub. Release After P&A (C-103Q) |

**QUESTIONS**

|   |               |
|---|---------------|
| <b>Abandoned Pipelines</b>  |               |
| <i>Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).</i>                        |               |
| Have all fluids have been removed from any abandoned pipelines  | Not answered. |
| Have all abandoned pipelines been confirmed to <b>NOT</b> contain additional regulated NORM, other than that which accumulated under normal operation | Not answered. |
| Have all accessible points of abandoned pipelines been permanently capped   | Not answered. |

|  |     |
|--|-----|
| <b>Last Remaining or Only Well on the Location</b>   |     |
| <i>Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.</i> |     |
| Have all electrical service poles and lines been removed from the location   | Yes |
| Is there any electrical utility distribution infrastructure that is remaining on the location  | Yes |
| Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan       | Yes |
| Have all the retrievable pipelines, production equipment been removed from the location  | Yes |
| Has all the junk and trash been removed from the location  | Yes |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 570546

**ACKNOWLEDGMENTS**

|  |   |
|--|---|
| Operator:<br>RILEY PERMIAN OPERATING COMPANY, LLC<br>29 E Reno Avenue<br>Oklahoma City, OK 73104 | OGRID:<br>372290  |
|  | Action Number:<br>570546                                |
|  | Action Type:<br>[C-103] Sub. Release After P&A (C-103Q) |

**ACKNOWLEDGMENTS**

|                                     |  |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection. |
|-------------------------------------|--|

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 570546

**CONDITIONS**

|  |   |
|--|---|
| Operator:<br>RILEY PERMIAN OPERATING COMPANY, LLC<br>29 E Reno Avenue<br>Oklahoma City, OK 73104 | OGRID:<br>372290  |
|  | Action Number:<br>570546                                |
|  | Action Type:<br>[C-103] Sub. Release After P&A (C-103Q) |

**CONDITIONS**

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| gcordero   | None      | 4/8/2026       |