



NEW YORKS ...

OIL CONSERVATION DIVISION
ACTED DISTRICT OFFICE
1000 RIO BRAZOS BLVD
ACTED WISCONSIN
215 S. WADE TRAIL, 5TH FLOOR
MILWAUKEE, WISCONSIN 53204

1132

4-1-26

07-20603

Property Name VPR A Well No. 212 Location: Unit 6 Section 14 Township T2N Range R18E

Well Status (Status of Producing) Initial PSL Tubing 120 Intermediate N/A Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	N/A	9	N/A	N/A
10 min	0		10		
15 min	0		11		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		N/A
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Down to nothing on BH / Down to nothing

By Monty Colangelo
Operator II
(Position)

Witness _____

E-mail address mcolangelo@wapitienergy.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 573582

CONDITIONS

Operator: Wapiti Operating, LLC 1251 Lumpkin Rd Houston, TX 77043	OGRID: 328741
	Action Number: 573582
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
smcfall	None	4/21/2026