

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St Francis, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 S St Francis  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. <b>30-007-20540</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name:  <b>VPR A</b>
8. Well No. <b>182 WDW</b>
9. Pool name or Wildcat <b>#97222</b> <del>Stubblefield Canyon</del> <del>Vermejo Gas</del>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☐ Other ☒ **Water Disposal** **#97222**

2. Name of Operator  
**EL PASO ENERGY RATON, L.L.C.**

3. Address of Operator  
**PO BOX 190, RATON, NM 87740**

4. Well Location  
Unit Letter **E** : **2166** feet from the **North** line and **1074** feet from the **West** line  
Section **28** Township **32N** Range **20E** **NMPM** **Colfax** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**8,191' (GL)**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **Mechanical Integrity Test** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well bore diagram of proposed completion or recompilation.

09/15/05 Performed MIT on tubing/casing annulus.  
Ran chart recorder. (Chart attached.) Held 500 psi for 30 minutes. Pressure test OK.

Witnessed by Donnie Trimble, Drilling Superintendent; Carl Everson, Contractor; and  
Tom Patten, Contractor.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *DR Langford* TITLE **Production Manager** DATE **09/27/05**  
Type or print name **Donald R. Langford** Telephone No. **(505) 445-6721**

(This space for State use)

APPROVED BY *[Signature]* TITLE **DISTRICT SUPERVISOR** DATE **9/28/05**  
Conditions of approval, if any:

**\* Next M.I.T 9/15/2010**

