


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NKMW/035645320

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Aid State SWD	Facility Type	Salt Water Disposal

Surface Owner	State	Mineral Owner	Lease No. API# 30-015-29569
---------------	-------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	14	17S	28E	660	SOUTH	1330	EAST	EDDY

Latitude 32 49.797 Longitude 104 08.589

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	300bbls	Volume Recovered	298bbls
Source of Release	Water Tank	Date and Hour of Occurrence	06/28/2010	Date and Hour of Discovery	06/28/2010 5:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD		
By Whom?	Josh Russo	Date and Hour	06/29/2010 1:10 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A fiberglass collar broke while working on a water tank. The collar has been replaced and the tank has been put back into service.

Describe Area Affected and Cleanup Action Taken.*

Initially we released 300bbls of produced water from the water tank at the Aid State SWD facility. We were able to pick up 298bbls of produced water with a vacuum truck. The entire release was contained inside the dike walls of the facility, which is lined with a 40 mil liner. All of the contaminated gravel has been removed and replaced with clean gravel. The locations has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By	
Title:	HSE Coordinator	Approved by District Supervisor:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	AUG 09 2011
Date:	06/14/2011	Expiration Date:	NA
Phone:	432-212-2399	Conditions of Approval:	NA Final
		Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-520

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, June 14, 2011 7:28 AM
To: Bratcher, Mike, EMNRD
Subject: Final C-141 - Aid State SWD
Attachments: AID STATE SWD -- DATE OF RELEASE -- 06-28-2010.pdf

Mr. Bratcher,

Please see attached the C-141 Final Report for a release that occurred on 06/28/2010. I wanted to make sure you had the Final C-141 Report for your records.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.