<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 1301 W Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action	
MMLB 1122240834	OPERATOR ☑ Initial Report ☐ Final Report
Name of Company BOPCO, L.P. 260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Remuda Basin 25 State #1	Facility Type E&P
Surface Owner State of N.M. Mineral Owner	er State Lease No E5894
LOCATION OF RELEASE	
	rth/South Line Feet from the East/West Line County
1 25 23S 29E	Eddy
Latitude_N 32.288041	Longitude W 103.936333
NATURE OF RELEASE	
Type of Release: Produced water and condensate	Volume of Release: 95 bbls of Volume Recovered: None
	produced water and less than 1
Source of Release 200 bhl produced water texts	bbl condensate. Date and Hour of Occurrence Date and Hour of Discovery
Source of Release: 300 bbl produced water tank	6/4/11, between 5 pm and 11 pm 6/5/11 9:00 a.m.
Was Immediate Notice Given?	If YES, To Whom?
☐ Yes ☐ No ☐ Not Requir	ed Mike Bratcher
By Whom? Tony Savoie	Date and Hour 6/5/11 7:30 p.m.
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.
☐ Yes ☒ No	
If a Watercourse was Impacted, Describe Fully.*	RECEIVED
	JUN 16 2011
Describe Cause of Problem and Remedial Action Taken.* The 300 bbl the next morning, all of the water had soaked into the ground inside the well was shut in the morning of 6/5/11.	water tank was struck by lighting the evening of 6/4/11, the pumper discovered it earthen containment. There was no evidence of Virgany where all the Sabrity. The
containment area on the caliche well pad. Samples were collected a 2 f and Chlorides. It appears the vertical extent did not exceed 3 ft. below	100 sq. ft. inside the containment area and approximately 300 sq. ft. outside the ft. intervals to a depth of 12 ft. below ground surface on 6/8/11 and analyzed for TPH ground surface. A copy of the analytical results are attached. We plan on excavating diation will follow the NMOCD recommended guidelines for the remediation of
regulations all operators are required to report and/or file certain releas public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remed	to the best of my knowledge and understand that pursuant to NMOCD rules and be notifications and perform corrective actions for releases which may endanger the NMOCD marked as "Final Report" does not relieve the operator of liability diate contamination that pose a threat to ground water, surface water, human health rt does not relieve the operator of responsibility for compliance with any other
	OIL CONSERVATION DIVISION
Signature: Tony Sancie	Approved by Distr Big Stept Bison Mile Brancisco
Printed Name: Tony Savoie	
Title: Waste Mgmt.& Remediation Specialist	Approval Date: AUG 1 0 2011 Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:
Date: 6/17/11 Phone:432-556-8730	Remediation per OCD Rules &
Attach Additional Sheets If Necessary	Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 9/10/2011