District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

MLB 1	O	OPERATOR											
Name of Company OGRID N					ıber	per Contact							
Yates Petroleum Corporation 25575					-	Amber Cannon							
Address						Telephone No.							
105 S. 4 TH S	Street			575-748-1471									
Facility Name API Number						Facility Type							
Martha AIK Federal #1 30-015-26549						Battery							
Surface Owner State Mineral Owner State													
State				NM-65417									
	Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
Unit Letter	Section	Township	Range Fo	Feet from the	North	/South Line	Feet from the	e East/	East/West Line				
P	11	22S	31E 330'			South	430'		East	Eddy	Eddy		
Latitude 32.39966 Longitude 103.74086													
NATURE OF RELEASE													
Type of Release						Volume of Release			Volume Recovered				
Produced Water; Crude Oil						30 B/PW;	5 B/O	0 B/PW; 5 B/O					
Source of Release							lour of Occurr	ence		Hour of Di	scover	y	
Knockout ga			7/8/2011; AM 7/8/2011; AM										
Was Immedi	ate Notice (equired	If YES, To Whom?										
By Whom?			Date and Hour										
Robert Asher/Yates Petroleum Corporation						7/8/2011, PM							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. N/A							
If a Watercourse was Impacted, Describe Fully.* N/A RECEIVED													
N/A RECEIVED													
Describe Cause of Problem and Remedial Action Taken.*													
	11 gashet on a knowledge of the water to ophi. The well and the knowledge were state hi.												
Describe Are	a Affected	and Cleanup	Action Tak	en.*		11 >		. \	411818	D ARTE	ESIA	1.,	
Describe Area Affected and Cleanup Action Taken.* An approximate area of 40' X 15' (all released water was contained in bermed battery). A vacuum truck was called to fix the goalect and along up the importance area. Ponth to Cround Water > 100' (approximated) 150' 200' 11. T32S P31F per Trand													
	was cancel to fix the gasket and clean-up the impacted area. Depth to Ground water: >100 (approximately-150 ; Section 11, 1225-K51E, per 17em												
Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
		iddition, NMC ws and/or regi		tance of a C-141	report d	loes not reliev	e the operator	of respon	sibility for c	compliance	with ar	ny other	
rederal, state	, or rocar ra		OIL CONSERVATION DIVISION										
Signature: AM JOHN CAMMA						OIL CONSERVATION DIVISION							
						Signed By Mily Benerica							
VVIII VIII VIII VIII VIII VIII VIII VI						Approved by District Supervisor:							
Printed Name	e: Amber C	annon						11501.					
Title: Envise	nmantal Da		Approval DaAUG 1 5 2011 Expiration Date:						ĺ				
Title. Elivito	innemai Re	gulatory Ager	it Trainee			Approvai Da	י ו טעא	-011	Expiration	Date.			
E-mail Addre	ess: acanno	n@yatespetro	leum.com			Conditions of	f Approval:			A ++= -1	—		
						1 Attached I							
Date: Friday, July 22, 2011 Phone: 575-748-4111						Remediation per OCD Rules &							
Attach Additional Sheets If Necessary Attach Additional Sheets If Necessary Phone: 5/5-/48-4111 Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 2PA-84												-01/5	
					PR	OPOSALNO	JI LAILEK II	7-41V:		ON		070	

Bratcher, Mike, EMNRD

From: Bob Asher [BobA@yatespetroleum.com]

Sent: Friday, July 08, 2011 3:55 PM

To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD

Cc: Jerry Fanning; Amanda Trujillo; Amber Cannon; Jeremy Haass

Subject: Release (Martha AlK Federal Battery)

Mike.

Yates Petroleum Corporation is reporting a release at the following location.

Martha AIK Federal Battery 30-015-26549 Section 11, T22S-R31E Eddy County, New Mexico

Date/Time of Release: 7/8/2011

Released: Approximately 6 B/O & 30 B/PW

Recovered: Not known at this time

Oil and produced water contained within the bermed battery.

A C-141 Initial Report will be submitted with complete details.

Thank you.

Robert Asher

Senior Environmental Regulatory Agent Yates Petroleum Corporation 575-748-4217 (Direct) 575-365-4021 (Cell) boba@yatespetroleum.com